

Income (PIP)

Date: 17.04.2023  
Time: 10:05:09  
Page: 1

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305551148  
REGN NO : SHC7009U  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4A)  
DATE OF REGN : 28.04.2022  
DATE/TIME IN : 17.04.2023 09:50  
ACCIDENT DATE : 14.04.2023

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2534-A	COVER FRONT BUMPER#	Set 1	586.18	25.00	439.63	R
0002	04-01-0302-2267-G	BUMPER CLIPS	? 10	22.00	25.00	16.50	X NW
0003	04-01-0302-2696-G	GRILLE SUB-ASSY#	? 1	438.00	25.00	328.50	X NW

SUB-TOTAL : 784.63

JOB NATURE

0000	L	PANEL BEAT	400.00	350
0001	SP	SPRAYPAINT CHARGE	300.00	

SUB-TOTAL : 700.00

TOTAL : 1,484.63

MVA NAME & SIGNATURE  
DATE:

SURVEYOR NAME & SIGNATURE  
DATE:

AUTHORISED : YES / NO

2 days

= \$650/H  
PIP =

17/4/23 230pm

PIP  
18km/h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: