

Income (PIP)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.04.2023

Time: 10:05:09

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305551148
REGN NO : SHC7009U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 28.04.2022
DATE/TIME IN : 17.04.2023 09:50
ACCIDENT DATE : 14.04.2023

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2534-A	COVER FRONT BUMPER#	Set 1	586.18	25.00	439.63	R
0002	04-01-0302-2267-G	BUMPER CLIPS	? 10	22.00	25.00	16.50	X NW
0003	04-01-0302-2696-G	GRILLE SUB-ASSY#	? 1	438.00	25.00	328.50	X NW

SUB-TOTAL : 784.63

JOB NATURE

0000	L	PANEL BEAT		400.00		350	
0001	SP	SPRAYPAINT CHARGE				300.00	250

SUB-TOTAL : 700.00

TOTAL : 1,484.63

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE: 2 days

PIP = 600
~~1500~~
1714923 230pm
11km/g

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: