

ASS. REC. BY:

REF:

AGZ/ 23004415/Kg

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To inspect Vehicle No: _____

at Workshop m/s LINK

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW 5746Y Yr Regn: 11.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey C.C. 1356Colour: M. D. Blue AC: Insured / Std / NI / NASp. Reading: 79019 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC189CFE205011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD/Rim or

Tyre Size: F: _____

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 8 mmL/Bal. 7 mm L/Bal. 8 mmD.O.A. 26/4/23 D.O.I. 15/5/2023

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Wesp. Said no. 2nd party, Part by part repair

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS. \$ _____

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

来發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0031951
Chua Jen-Ai

Page 1 of 2
Your ref. TP-SMN 9141P AGI
Job No. 73551
Our ref. 23.04.44
Payment
Date 28/4/2023

Attn

Vehicle No SKW 5746Y
Vehicle Model : Honda Odyssey
Accident on ... 26/4/2023

NOT Authorised
Recovery B4 repair
4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Tailgate	1,282.50	20.00	<i>Bu</i> 1,026.00 ✓
1.00	Pc	Honda logo emblem	38.70	20.00	<i>na</i> 30.96 ✓
1.00	Pc	Rear bumper	987.50	20.00	<i>Bu</i> 790.00 ✓
1.00	Set	Rear windscreen mouldings	252.80	20.00	<i>na</i> 202.24 ✓
Labour & Misc:					
1.00		To dismantle + refix rear windscreen	160.00		160.00 <i>12d</i>
1.00		To supply sealant	40.00		40.00 ✓
1.00		To check/clear fault codes after repair	80.00		80.00 <i>7</i>
1.00		To transfer parking sensors + reversing camera	80.00		80.00 <i>5d</i>
1.00		To dismantle + renew parts	450.00		450.00 <i>400d</i>

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身 20 个工位，准确的测量方式和大型铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-angier and the support ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO deluxe oven heater for re-spraying all motor vehicles."

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-012869-3
UEN: 199407590C

ESTIMATE

EST. No EST0031951
Chua Jen-Ai

Page 2 of 2
Your ref TP-SMN 9141P AG
Job No 73551
Our ref 23 04 44
Payment
Date 26/4/2023

Attn

Vehicle No SKW 5746Y
Vehicle Model : Honda Odyssey
Accident on : 26/4/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (Pearl paint)	600.00		600.00

50d

Sub-Total 3,459.20
GST 8.00% 276.74
Total S\$ 3,735.94

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修。还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/04/2023 17:47 (SGT)
Reported by	Actual Driver
Date of Accident	26/04/2023 07:25 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW5746Y

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHUA JEN-AI
NRIC No	S7906627C
Email Address	THETRAVELER38@GMAIL.COM
Mobile Phone No	(Phone) +65-98428188
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7220121651

DRIVER

Name of Driver	KENNETH CHAN
NRIC No	S7929002E
Date Of Birth	28/09/1979
Occupation	Indoor

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Police Officer together with the Accident Report.
3. Information provided must be as true & correct as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or who have insured vehicle(s) involved in this accident (all insured (s) who have insured vehicle (s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Machinery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my insurances or responding to any enquiries my insurances;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packing, etc.); and
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Accident Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRICID card)

76 Apr 2023
3:13 PM

Sketch Plan

