

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	ICE BHD	Ref	CS3/LPC23002481/Wqy3m4-	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date		
			Cod	le: LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 9720R	Veh. Inspected	SLE 8875X	
	Policy No.	Z22VC05011324	Coverage (\$)	0.00	
	Claim No.	22/23/23/VC05/027076	Excess (\$)	0.00	
	Assign From	CHARMAINE KONG	Assign Date	02/05/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11112739	Colour	WHITE	
	Odometer	108152 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	тоуо	7 mm	
	L/H Front Tyre	215/55 R17	TOYO	7 mm	
	R/H Rear Tyre	215/55 R17	TOYO	7 mm	
	L/H Rear Tyre	215/55 R17	TOYO	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/03/2023	Inspection Date	08/03/2023	
	Survey held at	KARR AUTOWORKS PTE LTD			
		BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				