

Scanned with CamScanner

Date/Time: 28.04.2023 14:57

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5894813

JC NO305552997

OMER

S COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

REGN NO.:
SHC1196B

MAKE:
HYUNDAI

MODEL
I-40

YR OF MANU.
29.12.2016

CHASSIS CODE
KMHLB41UMHU097728

MILEAGE

FUEL
E.....1/2.....F

DATE/TIME IN
28.04.2023 11:20

TARGET DATE

COMPLETION DATE/TIME:

JUNT CARD NO.


JOB DESCRIPTION

Accident Date: 28.04.2023
Time: 3P 28.04.2023

NO

LABOR CODE

DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

Vehicle No.: SHC1196B

YY

Vehicle No.: SHC1196B

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

Singapore

Loke Wei Yong

LKK

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/04/2023
Vehicle Reg. No.:	SHC1196B	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	29/12/2016
Vehicle Colour:	BLUE	Chassis No:	KMHLB41UMHU097728
Engine No:	D4FDGU700056		
Odometer:	684029 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	8,801.82
Miscellaneous Items	11.00
Labour	1,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,732.82
+ GST 8.00% (S\$)	858.63
Nett Amount (S\$)	11,591.45

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System