



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP23004464/Uvy3m4	
BLK 1 KAKI BUKIT AVE 6			Date: 29/05/2023	
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE				
417883				
ON BEHALF OF LEE HONG LIANG			Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected		SKX 6649H
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		03/05/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VIOS G GRADE (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MHFBT9F3606051770	Colour	GREY	
Odometer	66615 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	YOKOHAMA	7 mm	
L/H Front Tyre	195/50 R16	YOKOHAMA	7 mm	
R/H Rear Tyre	195/50 R16	YOKOHAMA	7 mm	
L/H Rear Tyre	195/50 R16	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date		27/04/2023	Inspection Date	
			03/05/2023	
Survey held at		BLUWEL AUTOMOTIVE SERVICE PL		
		BLK 1 KAKI BUKIT AVE 6		
		#01-28/53/55/56 (MAIN OFFICE)		
		SINGAPORE 417883		
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	