

ASS. REC. BY:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: SLL 13H EQ  
 Policy No. \_\_\_\_\_  
 Claims No. DM23HO00917  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vahr \_\_\_\_\_

Veh No: SHD4880J Yr Regt: 07 NOV 2019  
 Type: M.Gar/M.Cycle/Bus/Van/Lorry/Taxi/Prime Mover/L  
 Truck/Trailer or \_\_\_\_\_  
 Make: HYUNDAI IONIQ 'CC: 1580  
 Colour: Blue AC: Insured/Std/NA  
 Sp. Reading: 564565 Y/Radio: Insured/Std/NA  
 Eng No: \_\_\_\_\_  
 Ch No: KMHCF51C/LU188404  
 Gen. Cond: Good/Fair/Poor/Burnt  
 Steering: In order/Jammed/Leaked/Burnt or  
 Brake: In order/Jammed/Leaked/Burnt or  
 Mod: NA/S/Rim/STD/A/Rim, or  
 Tyre Size: F: 175/65R15  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The vahr had commenced its  
 repair at the time of inspection.



Est. or Market Value: \$  
 IDAC Accident Report: \_\_\_\_\_ Consider: Yes or No  
 GIA / PR Score: \_\_\_\_\_ Consider: Yes or No  
 Est. Repairs: 3 days Rest: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

BS/DUN/EXNOVA/GY/FS/LZA/MIC/OHTSU/PIR/SUMI  
 TOYO/YOKO or Westlake  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 5 mm  
 L/Bal. 6 mm L/Bal. 5 mm  
 D.O.A. 01/05/23 D.O.L. 03/05/23 4pm  
 Survey held at CDGE  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof or

CA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
30/5/23	Irfan confirmed LS \$2000 (Red 4154.32, 67%)

Date/Time, File Pass to? ☐ : Prel. Report  
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) 31/5/23-typist

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:  
 Transportation: \_\_\_\_\_  
 3 + RT: \$ \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_

Report Format: Merimen  
 Lump Sum / L.B.L: (\$ 2000)

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	01/05/2023
Vehicle Reg. No.:	SHD4880J	Driveable?	
Party At Fault:	UNKNOWN		

  

Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	07/11/2019
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVLU188404
Engine No:	G4LEKU402966		
Odometer:	564565 KM		

  

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	5

  

Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
-------------------	--

	Amount
<b>COST OF CLAIMS</b>	<b>4,374.32</b>
Parts	0.00
Miscellaneous Items	1,780.00
Labour	0.00
Paintwork Labour	0.00
Towing	
<b>Gross Total (S\$)</b>	<b>6,154.32</b>
<b>+ GST 8.00% (S\$)</b>	<b>492.35</b>
<b>Nett Amount (S\$)</b>	<b>6,646.67</b>

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System