



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB3576X
Case Reference Number	BUS/04/23/5020
Registration Date	2/2/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Zhu Peng
Type of Accident	Side Swipe
Accident Date and Time	4/13/2023 5:10 PM
Accident Reported Date and Time	4/25/2023 2:03 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3576X - RIGHT REAR PORTION SJC6500X (TP) - INSURED WITH AIG
Prepared Date and Time	5/3/2023 1:46 PM
Chassis Number	SFD76CLR5EMTL3728
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$874.82	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,934.82	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	03/05/2023 1:58 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Taufik 97495749
WP 3/5/23 E 350
Resumy after repair
taufik C/khank.wm

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/05/2023

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	795
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	708
Total Spray Painting & Panel Beating	\$878.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011253		2038001L24	Door, Fuel Filler Access	1.00	\$375.00	10.00	\$337.50	Replace	XXX BT✓
6011242	BODY RH	30106514	PANEL, EXTERIOR:R/H,F OR ADL DD BUS	1.00	\$511.14	10.00	\$460.03	Replace	XXX BT✓
6011242	BODY RH	30106514	PANEL, EXTERIOR:R/H,F OR ADL DD BUS	1.00	\$464.09	100.00	\$0.00	Repair	Rx
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	8.00	\$37.00	0.00	\$296.00	Replace	XXX NEC✓
Total					\$1,387.23		\$1,093.53		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									