

ASS, REG, BY:

REF:

NS/INC23004574/Snc

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No

Est. Repair: 3 days Rest: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN/OUT

Veh No: SH67513

Yr Reg: 15149/716

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Van / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai 1-40

CC 685

Colour: blue

AC: Insured / Std / NI / NA

Sp. Reading: 884240

TR: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C No: kmhL341

VRHGV093512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N / S / Rim / STD / Rim, or

205/60R16

Tire Size: F: 205

R: 60

R: 195/65 R16

BS/DUN/EXNOVA/GY/FS/LIZA/MG/OHTSU/PR/SUMI/

TOYO/YOKO or

m/s + lane

Front

Rear

R/Bal: 5 mm

R/Bal: 6 mm

L/Bal: 5 mm

L/Bal: 6 mm

D.O.A: 20/4/23

D.O.A: 21/4/23 2pm

Survey held at

comfort

Des. of Damages: Frt / Rear / C/S / N/S / U/C / Roof or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date/Time, File Pass to?

1) 22/05/23

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format:

Lump Sum / L.B.J: (\$ \_\_\_\_\_)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

3 + 12.5

Photos:

Others:

TOTAL

am: ARC Repair TP(CLSO)1

Date/Time: 21.04.2023 11:35

Page : 1

**JOB CARD** Sales Order: 5893877

JC NO 305552217

OMER  
S COMFORT TRANSPORTATION PTE LTD  
7010045  
OMER NO. 383 SIN MING DRIVE  
ESS Singapore SINGAPORE 575717  
65508755  
(R) (O)  
(P)

REGN NO. SH 6751J	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 20.04.2023 18:00
YR OF MANU. 15.09.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093512	COMPLETION DATE/TIME:


JUNT CARD NO.

Accident Date: 20.04.2023  
ATURE: 3P.20.04.23/C

JOB DESCRIPTION

NO LABOR CODE

DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

o.: SH 6751J JU INCOME

Vehicle No.: SH 6751J

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard