

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23004588/Any3m4	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	21/06/2023	
	ATTN: RAJESWAR	Υ		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJQ 1978P	Veh. Inspected	k	SLP 7421X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1221138-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		05/05/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTDGG20W70J007337	Colour		WHITE	
	Odometer	88569 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Front Tyre	195/65 R15	MICHELIN		6 mm	
	R/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
	L/H Rear Tyre	195/65 R15	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
	D7 ((V)) (OLO OLL D)	- 17 (ILO.			· ·	
5.	General Information					
	Accident Date	02/05/2023	Inspect Date /	Time	08/05/2023 ( 06:05 PM )	
	Survey held at	HD PERFECT AUTOWORK PTE	LTD			
	,	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.					
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.  Estimate Days of Repair					
J.J.	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					