



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662823
Accident Reporting Number : 68662672

Date Generated : 05/05/2023
User ID : BoonChewTay

TP
66
APV L-4
R-4

Section A - Accident Details

Registration Number	SHD6186S
Case Reference Number	TAX/05/23/2013
Registration Date	3/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	WONG CHONG PENG (HUANG ZHONGPING)
Type of Accident	Head To Side
Accident Date and Time	4/5/2023 9:24 PM
Accident Reported Date and Time	5/5/2023 9:55 AM
Surveyor Required?	No
Surveyed by	
Vehicle Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24118341
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	5/5/2023 1:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,636.00	\$0.00
Total Spare Part Cost	\$6,507.26	\$0.00
Total Other Cost	\$796.88	\$0.00
TOTAL COST	\$9,785.14	\$0.00
Temp Sum Total	\$9,800.00	\$0.00
Number of Repair Days	8.0	3 days
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	05/05/2023 1:27 PM	
Signature	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> <i>Henrich</i>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Quotation Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/05/2023
User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION	\$845.00 <i>200</i>	
Total Labour	\$845.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00 <i>200</i>	
O RESPRAY REAR PANEL	\$220.00 <i>?</i>	
O RESPRAY BUMPER BEAM	\$220.00 <i>?</i>	
O RESPRAY TAIL GATE	\$378.00 <i>X</i>	
O RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00 <i>150</i>	
O RESPRAY REAR SPARE TYRE PANEL	\$220.00 <i>X</i>	
Total Spray Painting & Panel Beating	\$1,636.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00 <i>X</i>	
O CHECK WIRING AND SYSTEM FUNCTION	\$120.00 <i>20</i>	
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00 <i>X</i>	
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00 <i>50</i>	
O REPLACE SUNDRY PARTS	\$100.00 <i>X</i>	
O PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$296.88 <i>✓</i>	
Total Other Costs	\$796.88	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	<i>BT ✓</i>
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	<i>?</i>
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	<i>NA ✓</i>
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	<i>NA ✓</i>
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	<i>NA ✓</i>
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	<i>NA ✓</i>
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	<i>NA ✓</i>
		5259968030	STOPPER, RR BUMPER, RH & LH	1.00	\$4.80	25.00	\$3.60	Replace	<i>NA X</i>
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	<i>NA X</i>
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace	<i>NA X</i>
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace	<i>?</i>
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace	<i>?</i>
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	<i>NA ✓</i>
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	<i>BT ✓</i>
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	<i>?</i>
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace	<i>?</i>

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662823
Accident Reporting Number : 68662672

Date Generated : 05/05/2023

User ID : BoonChewTay

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace	SM X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	SM ✓
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace	?
		9018906029	REAR BUMPER GROMMET SCREW	1.00	\$2.20	25.00	\$1.65	Replace	X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	10.00	\$440.10	Replace	X
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$489.00	10.00	\$440.10	Replace	X
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	10.00	\$489.96	Replace	X
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	10.00	\$489.96	Replace	X
		8149747020	COVER, REAR COMBINATION LAMP, RH	1.00	\$69.90	25.00	\$52.43	Replace	X
		8149847020	COVER, REAR COMBINATION LAMP, LH	1.00	\$69.90	25.00	\$52.43	Replace	X
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace	X
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$281.60	25.00	\$196.20	Replace	X
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	?
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	25.00	\$928.80	Replace	SM X
		6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	1.00	\$402.50	25.00	\$301.88	Replace	SM X
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace	X
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	SM -
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	SM -
		6935047050	TAIL GATE LOCK ASSY, BACK DOOR	1.00	\$505.50	10.00	\$454.95	Replace	SM X
		6932147010	TAIL GATE LOCK COVER, BACK DOOR	1.00	\$32.70	25.00	\$24.53	Replace	SM X
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace	SM -
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	SM ✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	SM ✓
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace	SM X
		5831147130	SPARE TYRE PANEL, PAN, REAR FLOOR	1.00	\$630.30	25.00	\$472.72	Replace	SM X
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	SM X
					\$10,237.00		\$8,171.07		

Used Spare Parts / Material Usage After Surveyor Signed off

Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/05/2023 13:40 (SGT)
Reported by	Actual Driver
Date of Accident	04/05/2023 21:24 (SGT)
Exact Location of Accident	Bras Basah Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6186S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXX369K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662672
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-23100854MFSH

DRIVER

Name of Driver	WONG CHONG PENG (HUANG ZHONGPING)
NRIC No	SXXXX349J
Date Of Birth	25/02/1975
Occupation	Outdoor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revoke policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

RAY 04/05/2023

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

A.

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

