



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI23004602/Uvy3q2

Date: 29/05/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 1762G	Veh. Inspected	SJQ 998M
Policy No.	P10493644R02	Coverage (\$)	0.00
Claim No.	C10022027 /CD	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	05/05/2023

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GK82002284	Colour	GREY
Odometer	60349 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	6 mm
L/H Front Tyre	185/60 R15	DUNLOP	6 mm
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/04/2023	Inspection Date	10/05/2023
Survey held at	PROMPT AUTO SOLUTIONS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**