

ASS. REG. BY:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES / OD RES / EVA / INV / MY  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: FBT 3743R Inc  
 Policy No. \_\_\_\_\_  
 Claims No. MT/1219363-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Valt: \_\_\_\_\_

(Policy Condition)

Remark: The vch had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Est. or Market Value: \$ \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Score: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repair: 2 days Res: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN/OUT

Veh No: Shc7958E Yr Regt: 30/10/2020  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover L  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai 10th cc 1580  
 Colour: Yellow AC: Insured / Std / NA  
 Sp. Reading: 126541 T/Race: Insured / Std / NA  
 Eng/No: \_\_\_\_\_  
 C/No: Kmh10510/LV184615  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: None / Jammed / Leaked / Burnt or  
 Brake: None / Jammed / Leaked / Burnt or  
 Mod: NS / S/Rim / STD / R/Rim or  
 Tyre Size: F: 2195/65R15  
 R: 2195/65R15  
 BS/DUN/EXNOVA/GY/FS/LZA/MIC/OHTSU/PR/SUMI/  
 TOYO/YOKO or WST Lorie  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 5 mm R/Bal: 5 mm  
 L/Bal: 5 mm L/Bal: 5 mm  
 DOA: 20/4/23 D.O.L: 21/4/23 3pm  
 Survey held at: Comfort  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                        |
|-------------|---------------------------------------------|
| 9/5/23      | Irfan confirmed LS \$1150 (Red 1282 24.52%) |
|             | Balance:                                    |
|             | yearly:                                     |
|             | mv:                                         |
|             | Nir:                                        |

Date/Time, File Path to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
 Date/Time, File Path to?

2) 16/5/23-typist

Report Format: TP

Lump Sum / L.B. (\$ 1150)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS: \$

Picks:

Others:

TOTAL

Date/Time: 21.04.2023 08:36 Page : 1

Team: ARC Repair TP(CFS0)1

**JOB CARD** Sales Order: 5893830

JC NO305552212

STOMER

MS CITYCAB PTE LTD  
STOMER NO 7010070  
DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65551188 (R) (P) (O)

COUNT CARD NO.

REGN NO:

SHC7958E

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

20.04.2023 13:45

DATE/TIME IN

YR OF MANU

30.10.2020

TARGET DATE

CHASSIS CODE

KMHC851CVLU184615

COMPLETION DATE/TIME:

JOB DESCRIPTION


Ident Date: 20.04.2023

NATURE: 3P 20.04.2023

S/NO

LABOR CODE

DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.:

SHC7958E

CHIANG

Vehicle No.:

SHC7958E

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard