

# COMFORTDELGRO ENGINEERING PTE LTD

Updated 1 November 2020

## REPAIR ESTIMATE

LKK-

DATE: 14.03.2023

MODEL: Hyundai i40

VEHICLE NO.: SH 8326R

INSURANCE: CHINA TAIPING

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Wing Mirror RH	1		<i>del</i> \$670.00
	SUB TOTAL			\$670.00
	LESS 20%			\$134.00
	DISCOUNTED PARTS TOTAL			\$536.00
	<u>Labour Charge</u>			
	Panel Beating			<i>120</i> \$150.00
	Spray Painting Charge			<i>100</i> \$150.00
	TOTAL LABOUR			\$ 300.00
	ESTIMATE TOTAL			\$ 836.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

*Tanpin 97495749*  
*WR 14/3/23 @ 130m*  
*01 day*  
*1/3 Resurvey after repair*  
*tanpin c/hkauto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

### Workshops

59 Loyang Drive Singapore 508968

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 14.03.2023 08:12

Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5889294

JC NO305548450

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

JUNT CARD NO.

REGN NO.:

SH 8326R

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

13.03.2023 15:20

YR OF MANU.

11.01.2017

TARGET DATE

CHASSIS CODE

KMHLB41UMHU098188

COMPLETION DATE/TIME:

### JOB DESCRIPTION

Accident Date: 11.03.2023

ATURE: 3P 11.03.2023

'NO

00010

LABOR CODE


PB

00020

SP

DESCRIPTION  
PANEL BEATING-SH 8326R-TP  
SPRAYPAINT CHARGE

FRONT



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SH 8326R

LIMITS

Vehicle No.:

SH 8326R

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard