

DATE:

S.mg

REF:

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / UNV / MV

To Inspect Vehicle No:

at Workshop no:

of:

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vehc:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Sec:

Consistent? Yes or No

Est. Repairs:

2 days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

SHD 833H

Yr Reg:

22/06/2016

Type: M/Gar / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

CC 1.685

Colour:

Blue

AC: Insured / Std / N/A

Sp Reading:

849 273

Tyre: Insured / Std / N/A

Esp No:

Ch No:

KMBL B41 JMGU091568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / SRM / STD ARM, or

Tyre Size:

F: 195/65 R15

R:

BS / DUN / EXHVA / GY / FS / LZA / WIC / OHTSU / PRI / SUMI /

TOYO / YOKO or

Wag + 1 a/c

Front

Rear

R/Ral:

5

mm

R/Ral:

5

mm

L/Ral:

5

mm

L/Ral:

5

mm

D.O.A. 20/4/2023

D.O.L. 25/4/23 4pm

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

: Prel. Report

1)

Date/Time, File Return to?

: Final Report

2)

Report Format:

Lump Sum / L.B.J: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + R.R. 1.5

Photos:

Others:

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Date/Time: 25.04.2023 11:14

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5894176

JC NO305552508

CUSTOMER MS COMFORT TRANSPORTATION PTE LTD 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P) COUNT CARD NO.	REGN NO. SHD6833H	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 25.04.2023 10:05
	YR OF MANU. 22.06.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU091568	COMPLETION DATE/TIME:

Accident Date: 20.04.2023
NATURE: 3P 20.04.2023

JOB DESCRIPTION

LS

SJP


Income

3920Y

;/NO
100010

LABOR CODE
PB

DESCRIPTION
LUMP SUM REPAIR-SHD6833H-TP



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedgement Slip

Exit Pass

No.: SHD6833H LIMITS

Vehicle No.: SHD6833H

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard