

(08/11/13) We/

ASS. REC. BY: John

REF:

CS/EA 123004661/Rqy3

689F

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL 7946 U

at Workshop m/s

MOTOR IMAGE

of

25, LON KET 15

Insured:

EQ

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

69K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL 7946 U

Yr Regn: 2017 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester 2.0XTS/R c.c 1998

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

107544

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

2F1SJK8566082851

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKE or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/05/23

D.O.I.

17/05/23

Survey held at

Subaru

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 37K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

): S + RS SI

☐

: Interview (\$

): Photos

☐

: Tech. Invs (\$

): Others

☐

: Weekend (\$

Report Format :

Lump Sum / L.P. / (\$

TORIMAGE ENTERPRISES PTE. LTD.
5 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0123/2023
DATE : 06-MAY-2023

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
S(069110)
TEL :
FAX :

OWNER'S NAME : G SURESH KUMAR NAIR
ADDRESS : 22 BURNFOOT TERRACE

TELEPHONE NO : 96463172
S(459814)

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100503392-06 AIG
VEHICLE NO : SLL7946U
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20B899429
CHASSIS NO : JF1SJGK85GG082851
MILEAGE : 1 KM
DATE IN : 06/05/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/05/2023

Print Date : 06/05/2023
Print Time : 14:24:46

EE ENTERPRISES PTE. LTD.
KEE ROAD
RE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL7946U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST EQ INS-SLF6708D		
2	ZZ/001	DOA:01/MAY/2023 TIME:1425 HRS LOCATION:TOA PAYOH LORONG 6		
3	ZZ/002	REPLACE REAR BUMPER & BUMPER BEAM	3500.00	600
4	ZZ/003	RESPRAY REAR BUMPER & BUMPER BEAM	3000.00	520
5	ZZ/004	TRANSFER REVERSE SENSOR (OLD TO NEW BUMPER)	100.00	80
6	ZZ/005	FAULT DIAGNOSTIC (RESET)	280.00	
7	ZZ/006	SUNDRIES	100.00	20
TOTAL LABOUR CHARGES			6980.00	

SE ENTERPRISES PTE. LTD.
KEE ROAD
ORE 159097

SERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL7946U

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE R <i>de</i>	57704SG012 <i>de</i>			610.50	
2	BRKT SD R <i>RH ne</i>	57707SG080			14.80	
3	BRKT SD R LH <i>ne</i>	57707SG090			14.80	
4	BEAM COMPL R EU <i>?</i>	57711SG0219P			296.00	
5	COVER HOOK R <i>cut</i>	57731SG010NN			13.00	
6	CLIP BMPR *9PCS <i>ne</i>	909140007			21.60	
7	CLIP *2PCS <i>ne</i>	909140062			6.00	
SUB TOTAL			0.00	0.00	976.70	0.00
LESS DISCOUNT ()			0.00	0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	976.70	0.00
OVERALL TOTAL			976.70			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Subaru Forester 2.0i-L Sunroof

\$69,888 Instalment \$1,209/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	<i>i</i> \$16,280 / year
Reg. Date	10-Mar-2017 (3yrs 9mths 19days COE left)
Manufactured	<i>i</i> 2016
Mileage	122,689 km (19.8k / year)
Transmission	Auto
Engine Cap	1,995 cc
Road Tax	<i>i</i> \$1,208 / year
Power	110.0 kW (147 bhp) View specs of the Subaru Forester (2013-2019)
Curb Weight	<i>i</i> 1,566 kg
COE	<i>i</i> \$50,621
OMV	<i>i</i> \$15,690
ARF	<i>i</i> \$15,690
Dereg Value	<i>i</i> \$29,490 as of today
No. of Owners	<i>i</i> 1

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	689F
Vehicle No.:	SLL7946U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 May 2023
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	FA20B899429
Chassis No.:	JF15JGK85GG082851
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$19,237.00
Original Registration Date:	10 Mar 2017
First Registration Date:	10 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$19,237.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Mar 2027
PARF Rebate Amount:	\$12,504.00
COE Expiry Date:	09 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$19,256.00
Total Rebate Amount:	\$31,760.00

The information contained herein is correct as at 18 May 2023

OK

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL7946U

TOTAL LABOUR CHARGES	6980.00
TOTAL SPARE PARTS CHARGES	976.70
GRAND TOTAL	7956.70 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Repair - 48 reviews
17/05/23 @ 1120
3 days
Repair 84 part

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.