



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23004666/Avy3e2 Date: 03/08/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 839G	Veh. Inspected	SJE 228R	
Policy No.	P10563547R01	Coverage (\$)	0.00	
Claim No.	C10022091 /SR	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	08/05/2023	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDA STARIA	c.c	3470	
Engine No.	HIDDEN	Year of Reg.	2023	
Chassis No.	KMHYF814MPU096001	Colour	WHITE	
Odometer	1841 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	KUMHO	6 mm	
L/H Front Tyre	235/55 R18	KUMHO	6 mm	
R/H Rear Tyre	235/55 R18	KUMHO	6 mm	
L/H Rear Tyre	235/55 R18	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2023	Inspection Date	11/05/2023	
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	