

(08/11/13) wef
ASS. REC. BY: Rasm

REF:

CC4/AIS 23004671/Rya3


1202

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMD 10784
at Workshop m/s MOTOR IMAGE
of LENG KEO RD
Insured: AIS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 81K
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMD 10784 Yr Regn: 2018 / 1A44
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: SUBARU FORESTER 2.0i-L8/R.c.c 1995
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 086844 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 2F1S2SKC5JG111547
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / Rim / STD A/Rim or
Tyre Size: F: 225/60R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKE or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>30/04/23</u>		D.O.I. <u>10/05/23</u>
Survey held at <u>MOTOR IMAGE</u>		

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 54K

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	120I
Vehicle No.:	SMD1078U
Vehicle to be Exported:	No
Intended Deregistration Date:	10 May 2023
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	FB20YE29096
Chassis No.:	JF1SJ5KC5JG111547
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,642.00
Original Registration Date:	01 Aug 2018
First Registration Date:	01 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$13,642.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2028
PARF Rebate Amount:	\$10,231.00
COE Expiry Date:	31 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$16,191.00
Total Rebate Amount:	\$26,422.00

The information contained herein is correct as at 10 May 2023

OK

Subaru Forester 2.0i-L Sunroof

\$81,800 Instalment \$1,051/mth

PREMIUM AD

💰 Apply for 2.28% loan

♡ Shortlist

✔ Get Warranty



How much can you sell your car for?

Get FREE valuation

sgcar mart
quote

Overview Financial Photo Research

Depreciation	ⓘ \$14,140 / year
Reg. Date	30-Aug-2018 (5yrs 3mths 19days COE left)
Manufactured	ⓘ 2018
Mileage	85,670 km (18.2k / year)
Transmission	Auto
Engine Cap	1,995 cc
Road Tax	ⓘ \$1,208 / year
Power	110.0 kW (147 bhp)
Curb Weight	ⓘ 1,591 kg
COE	ⓘ \$34,381
OMV	ⓘ \$13,451
ARF	ⓘ \$13,451
Dereg Value	ⓘ \$28,343 as of today
No. of Owners	ⓘ 2
Type of Veh	SUV