




Service Request Details

Claim

S3M04M8A

Reference

CS3/HSB23004731/p3 

Loss Date

3 May 2023

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

4 May 2023 2:53:51 PM

Request Date

9 May 2023

Due Date

9 May 2024

Services

Pre-Repair Survey

Actions

Next Step

Complete work

More ▾

Vehicle Information

Incident Vehicle Registration #
GBH1043D

Make
TPVD

Model
Toyota

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages1	Invoices	History	Documents	Assessment	Metrics	Notes
-----------	----------	---------	-----------	------------	---------	-------




TYPE?

SENT9/5/23 5:41 PM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECTAssignment


BODYDear Winnie, Thank you for the assignment. Repaire...


TYPE?

SENT9/5/23 11:26 AM

FROMHO Winnie

SUBJECTAssignment

BODYHi, as spoken - pls email to TP legal request for ...


TYPE?

SENT9/5/23 11:15 AM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECTAssignment

BODYDear Winnie, According to the repairer M/s Kan Foo...
