

(08/11/13) Wf

ASS. REC. BY: PAME

REF: CS3/ASB 2300 4732/Rvp3

9031

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBN 7540Pat Workshop m/s EXCEL CYCLEof TOYOTA CROWN 2008 #01-112Insured: SHC 3042Z HIS

Policy No.

Claims No. S3M04MCE


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

16k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBN 7540P

Yr Regn:

2017 Juv

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YANAGHA C20300A Xmax 300 c.c 292

Colour

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

56835

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

M438 H081000010163

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-15

R:

150/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

05/05/23

D.O.I.

16/05/23

Survey held at

EXCEL CYCLE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 13K

11/5/23

ESTIMATE RANGE OF REPAIR / NO OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 11/5/23-typist

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	903I
Vehicle No.:	FBN7540P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 May 2023
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	H336E0010953
Chassis No.:	MH3SH081000010163
Maximum Power Output:	-
Open Market Value:	\$3,934.00
Original Registration Date:	22 Jun 2017
First Registration Date:	22 Jun 2017
Transfer Count:	4
Actual ARF Paid:	\$591.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	21 Jun 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,001.00
COE Rebate Amount:	\$2,468.00
Total Rebate Amount:	\$2,468.00

The information contained herein is correct as at 10 May 2023

OK

Yamaha Xmax 300

Listing Type

Paid Ad

Brand

Yamaha

Model

Yamaha Xmax 300

Engine Capacity

292cc

Classification

Class 2A

Registration Date

19/06/2017

COE Expiry Date

18/06/2027

(4yrs 1mths 8days COE left)

Mileage

35000km

No. of owners

-

Type of Vehicle

Scooters

SGD \$16800