

(08/11/13) WFF
ASS. REC. BY: RAME

REF: CS3/ASB 2300 4732/RVP3


9031

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FBN 7540P
at Workshop m/s EXCEL CYCLE
of TOYOTA AVANZA 2011 #01-112
Insured: FBS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 16k
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBN 7540P Yr Regn: 2017 / Jan
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: YAMAHA C2D300A XMAX 300 c.c 292
Colour: MULTI A/C: Insured / Std / NI / NA
Sp. Reading: 56835 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: M438 H081000010163
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 120/70-15
R: 150/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front	Rear
R/Bal. <u>4</u> mm	R/Bal. <u>4</u> mm
L/Bal. _____ mm	L/Bal. _____ mm

D.O.A. 05/05/23 D.O.I. 16/05/23
Survey held at EXCEL CYCLE

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 13K

ESTIMATE RANGE OF REPAIR / No of days - (2K-3K) / 3 days

Date/Time, File Pass to? : Prell. Report
1) : Final Report

Date/Time, File Return to?
2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____ Survey Fee: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____) Photos
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$) _____)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	903I
Vehicle No.:	FBN7540P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 May 2023
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	H336E0010953
Chassis No.:	MH3SH081000010163
Maximum Power Output:	-
Open Market Value:	\$3,934.00
Original Registration Date:	22 Jun 2017
First Registration Date:	22 Jun 2017
Transfer Count:	4
Actual ARF Paid:	\$591.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	21 Jun 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,001.00
COE Rebate Amount:	\$2,468.00
Total Rebate Amount:	\$2,468.00

The information contained herein is correct as at 10 May 2023

OK

Yamaha Xmax 300

Listing Type

Paid Ad

Brand

Yamaha

Model

Yamaha Xmax 300

Engine Capacity

292cc

Classification

Class 2A

Registration Date

19/06/2017

COE Expiry Date

18/06/2027

(4yrs 1mths 8days COE left)

Mileage

35000km

No. of owners

-

Type of Vehicle

Scooters

SGD \$16800