

ASS. REC. BY:

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s AS Auto service  
 of \_\_\_\_\_  
 Insured: CTI  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$571K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 04 d Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLC4434 Yr Regn: 29 APR 2016  
 Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Audi A3 c.c. 1395  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 335122 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZ8V0G1088096  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: NI / S/Rim / STD A/Rim. or  
 Tyre Size: F: 205 / 55 R16  
 R: 205 / 60 R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or F: Kumho R: Continental  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 12/11/22 D.O.I. 21/11/22 24Sp  
 Survey held at AS Auto service  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Est Repair cost  
\$3K - 4K

Balance: 41.6m  
 yearly: 16K  
 mv: 57K  
 NV: 32K

13/06/2023 Submit L/s \$5,100.00 @ 4 days (Red \$4,800.00/48%)  
\$7,700.00

High mileage - 5K = \$5  
 HRF 50% = 6809

Date/Time, File Pass to? 13/06/2023  
 1) Typist  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 \$ + RS \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_

Report Format: Paper Survey  
 Lump Sum / I.B.E. (\$ 45 \$5,100.00)

\$7,700.00

TOTAL