

ASS. REC. BY: Kenneth REF: SMR/23004702/K vy3

ASSIGNMENT

From: _____ Date: _____ Estimated Cost: _____ OD/TP/WS/TP RES/OD RES/EVA/INV/INV To Inspect Vehicle No: _____ at Workshop m/s: <u>Real Auto</u> of: <u>5032 01-305</u> Insured: <u>SHD 6191B</u> <u>4616</u> Policy No. _____ Claims No. <u>TAX/05/23/2024</u> Sum Insured: _____ Excess: _____ (Client's Record) Make of Veh: _____ (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td>N/S</td> <td>O/S</td> </tr> </table> Bal. or Market Value: _____ IDAC Accident Rpt: _____ Consistent? : Yes or No GIA / PR Seen: _____ Consistent? : Yes or No Est. Repairs: <u>03</u> days Res.: Yes or No Lum Sum: _____ % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: _____ Person Contacted: _____ Vehicle: IN / OUT	N/S	O/S	Veh No: <u>SMK 748P</u> Yr Regn: <u>06, 14</u> Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____ Make: <u>Volvo</u> <u>X60</u> <u>1989</u> Colour: <u>M. Brown</u> A/C: Insured / Std / NI / NA Sp. Reading: <u>134807</u> T/Radio: Insured / Std / NI / NA Eng/No: _____ C/No: <u>YU108400DE</u> <u>258P527</u> Gen. Cond: <u>Good</u> / Fair / Poor / Burnt Steering: In order / Jammed / Leaked / Burnt or Brake: In order / Jammed / Leaked / Burnt or Mod: NI / S/Rlm / STD / A/Rlm or Tyre Size: F: <u>235/60R18</u> R: _____ BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or <table border="0"> <tr> <td>Front</td> <td>Rear</td> </tr> <tr> <td>R/Bal. <u>8</u> mm</td> <td>R/Bal. <u>8</u> mm</td> </tr> <tr> <td>L/Bal. <u>8</u> mm</td> <td>L/Bal. <u>8</u> mm</td> </tr> <tr> <td>D.O.A. <u>8/5/23</u></td> <td>D.O.I. <u>17/5/2023</u></td> </tr> </table> Survey held at _____ Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or <u>01571</u> The U/C / Chassis frame / Body Structure affected due to collision.	Front	Rear	R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm	D.O.A. <u>8/5/23</u>	D.O.I. <u>17/5/2023</u>
N/S	O/S										
Front	Rear										
R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm										
L/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm										
D.O.A. <u>8/5/23</u>	D.O.I. <u>17/5/2023</u>										

Date / Time	Action / Instruction
1	PRS
18/5/23	<u>En report com 85-6K</u>

File Pass to? ☐ : Prell. Report

File Return to? ☐ : Final Report

18/5/23-typist

Format: _____

im / I.B.I: (\$ _____)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation
S - RS. SI
Fixings
Others
TOTAL

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)