

Havelock II, 2 Havelock Road #05-21, Singapore 059763 Tel: 9008 3740

Our Ref: 2023.0807.PD.JK/LN Writer : John Koh

Your Ref: Please Advise Executive : -

Direct Line : +65 9008 3740 Email : john@avalonlaw.sg /

22 June 2023 lara@avalonlaw.sg

LONPAC INSURANCE BHD

300 Beach Road #17-04/07 The Concourse Singapore 199555

Attn: Motor Claims Department

WITHOUT PREJUDICE

By Email Only

E: mt_claim@lonpac.com

Dear Sirs,

CLAIMANT: LEK WEI LI (NRIC NO. SXXXX534Z) ACCIDENT INVOLVING SMQ 4373D (OUR CLIENT) & YP 7009A AT OR ALONG 5 MANDAI LINK, #05-04 ON 5 MAY 2023

We refer to the above matter wherein we act for Mr Lek Wei Li, the registered owner of SMQ 4373D ("our client").

We are instructed by the abovenamed to claim damages against your insured in connection with the abovementioned accident with YP 7009A, which was insured by your goodselves.

We are instructed that the accident was caused by the negligence of the authorized driver, employee, agent and/or servant of your insured at the time of accident. As a result of the accident, our client's vehicle was damaged and he has been put to loss and expense.

Purely for the purpose of an amicable settlement, we are prepared to advise our client on the quantification as follows:

SPECIAL DAMAGES		AMOUNT		
a.	Cost of repairs	S\$	12,050.00	
b.	Loss of use (based on \$120.00/day x 9 days)	S\$	1,080.00	
c.	Tow fee	S\$	120.00	
	SUB TOTAL:	S\$	13,250.00	
TOTAL DAMAGES		S\$	13,250.00	

COST & DISBURSEMENTS		AMOUNT	
a.	Legal costs	S\$	900.00
b.	LTA search	S\$	26.75
c.	ACRA Bizfile search	S\$	5.50
d.	GIA report	S\$	31.00
e.	Survey report	S\$	741.00
f.	Incidentals	S\$	150.00
	SUB TOTAL:	S\$	1,854.25
GRAND TOTAL		S\$	15,104.25



Havelock II, 2 Havelock Road #05-21, Singapore 059763 Tel: 9008 3740

We enclose herewith the following documents for your retention: -

- 1) GIA report lodged by our client;
- 2) GIA report lodged by your insured;
- 3) Proforma invoice;
- 4) Surveyor's report;
- 5) Towing Invoice; and
- 6) Disbursement invoice(s) / receipt(s).

Please note that you should send to us an acknowledgement of receipt of this letter within **fourteen (14) days** of your receipt of this letter.

Should you fail to acknowledge receipt of this letter within **fourteen (14) days**, our client can commence legal proceedings against your insured without further reference to you.

Yours faithfully,

AVALON LAW CORPORATION

Enc

Cc. Client

Lim Chin Choo T/A Holie Trading Chiam Chia Zhen C/O Lim Chin Choo T/A Holie Trading 637 Veerasamy Road #01-121 Singapore 200637

By Certificate of Posting Only (Less Enclosures)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/05/2023 10:20 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 05/05/2023 13:30 (SGT) Exact Location of Accident 5 Mandai Link, #05 04, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Toyota

Vehicle Registration Number SMQ4373D

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LEK WEI LI NRIC No S8130534Z Email Address vinboylek@yahoo.com Mobile Phone No (Phone) +65-98432523 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Estima Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party

Vehicle Category Private car Transmission Auto CC 2362

INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd Policy Number / Cover Note Number MT/00867391/02

DRIVER

Name of Driver LEK WEI LI NRIC No S8130534Z Date Of Birth 23/09/1981 Occupation Indoor

Date Of Driving Pass 15/04/2002 Driving experience 21 YEARS AND 1 MONTH Gender Mobile Number (Phone) +65-98432523 Alt. Phone Number Email Address vinboylek@yahoo.com Address APT BLK 687A CHOA CHU KANG DRIVE #03-402 Address complement Postcode 681687 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Clear Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 5 MAY 2023, AT ABOUT 1330 HRS, MY VEHICLE (SMQ4373D) WAS PARKED AT 5 MANDAI LINK #05-04, I AM OVERSEA AND NOT INSIDE THE CAR. MY WORKER TOLD ME THAT VEHICLE B WAS SKIDDED AND COLLIDED ONTO MY REAR RIGHT SIDE BECAUSE ROAD SURFACE TOO WET ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number YP7009A Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category

Commercial vehicle

Name of Driver Work Permit No	CHIAM CHIA ZHEN G2257683L
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims,

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


VZN LEK 8/5/23

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

(Name as in NRIC/ID card)

Sketch Plan



V20HZ0ZZ

n 5 May 20 mandai L e that vel	03 , At nk *05-	about 1	m aerx	. My	vehale not inv	(SMQ)	43730) > (ar	was My	parked worker	at told
e that vel ad surface u	nde B 1 w uet.	wa stiddo	d and	colleded	onto	ny 100	r nyld	sHe	heause	

Declaration

I/We declare the foregoing particulars are true in every respect,

VZH LCK - 8/5/23

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

vJun2022



Contact us at

Hotline: (65) 6665 5555

E-mail: customerservice@directasia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act") Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore) Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No. : MT/00867391/02

Type of Coverage / Driver Plan : Car Comprehensive (Value Plan)

 1) Vehicle Registration No.
 : SMQ4373D

 Chassis No.
 : ACR507081517

2) Name of Policy Holder : LEK WEILI

3) Effective Date / Time of Commencement

of Insurance for the Purpose of the Act : 30/12/2022 00:00

4) Date/Time of Expiry of Insurance : 29/12/2023 23:59

5) Persons or Classes of Persons Entitled to Drive

(a) Any person who is named on the policy who is driving on the Policyholder's permission.

The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.

6) Limitations as to use'

Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. Grab Hitch will only be covered if this is the declared usage stated on your Policy Schedule.

'Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.

Sum Insured : Market Value

 Own Damage Excess
 : S\$ 900.00

 Windscreen Excess
 : S\$ 100.00

Choice of workshop : DirectAsia approved workshops

Finance company / Hire Purchase

Main driver : LEK WEILI
Named driver : None

Important Note: This policy is on a named driver basis. The Policyholder has to be named as the Main Driver or Named Driver to be covered. Any unnamed drivers will not be covered.

I/We hereby certify that the Policy to which this Certificate relates to is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 30/11/2022

Direct Asia Insurance (Singapore) Pte. Ltd.


Underwriting Manager

Company Registration: 200822611G











































































IMPORTANT NOTE: Please submit the completed Addendum form to the same Accident Reporting Centre with whom you submitted the Original Report. **ADDENDUM** (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No: SA1023580001 Vehicle Registration No: SMQ4373D Name (as shown in NRIC): __LEK WEI LI _____ NRIC/FIN/Passport No: __ (*Vehicle Driver/Policyholder) (*) Please delete as appropriate APT BLK 687A CHOA CHU KANG DRIVE #03-402 681687 Contact (Tel): 98432523 __ Mobile No.: __ Email Address: vinboylek@yahoo.com 1330 __ Time of Accident: _ Date of Accident: 05/05/2023 Place of Accident: 5 MANDAI LINK #05-04 Insurance Company: DIRECT ASIA (B) ADDITIONAL INFORMATION / AMENDMENTS: I have made a report on the above-mentioned accident and would like to include additional information or make the following amendments: TO AMEND EMAIL ADDRESS Reporting Centre Personnel's Signature Policyholder / Actual Driver's Signature

Name (as in NRIC/ID card):

Date:

vJun2022

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/05/2023 16:36 (SGT) Reported by **Actual Driver** Date of Accident 05/05/2023 14:30 (SGT) Exact Location of Accident Singapore Additional Location Information 5 MANDAI LINK (INFRONT OF #05-05) Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP7009A INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner **HOLIE TRADING**

VEHICLE PARTICULARS

Manufacturer Mitsubishi Model FUSO FK62FMZ1RDEB Variant Vehicle Category Commercial vehicle Transmission Manual 7545

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd Policy Number / Cover Note Number Z22VC05014892

DRIVER

Name of Driver CHIAM CHIA ZHEN Passport No/FIN G2257683L Address Address complement

Postcode Does Driver Own Other Vehicles? No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collided into Parked Vehicle Weather Conditions Clear

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Was anybody injured in the Accident? No
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1

Translator's name --Translator's ID --Translator's phone number --Translator's email --Original language used in the statement --
CIRCUMSTANCES OF ACCIDENT

REFER SKETCH ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration NumberSMQ4373DVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-Vehicle CategoryPrivate carName of Driver-Insurance Company Name-

SKETCH PLAN

4P7009A VEH NO lon pac INSURER DATE OF ACC

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Traffic Police Department for investigation.

- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s). who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law from which may be sited outside of Singapore, for one or more of the above Purpose 和利善堂金纸行 HOLIE TRADING

Reg No. 53289545B


Policyholder's Signature / Date & Time

is not the policyholder! / Date

Witnessed by Reporting Centre Perso (Name as in NRIC/ID card) E44 0 M

8 5 23 (45)

Sketch Plan



1

	nensive policy. Pls check		Reporting Onlly	
) Claim Own Policy () Claim Third party	(.	Reporting Only	
) Claim OD/ TP at other work etch Plan	shop (15 15 T	
EtGII FIBII				
#06	-05		5 Mandai	NUK
11.7			infront of #	FO5 -0
N N N			HEDOLINE	
		0. 11	2000 A	
(B)	7	H= Y1	P 7009 A	
		B = S	M Q 4373D	-
		linii		
port Hilliam				
Doa: 5/5/23	Time = 14.	Boho	Ins : lonpac	
While driving	at level 5	drivewa	y my left	
while driving rear type skid my long, hit or	ded due p	the wet	floor and	
my long, hit of	to parked (9)	CB).		
rear		1	1756.76	
		- 1		

Declaration

I/We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card) Huda




























110 Jurong East Street 13 #05-312 Singapore (600110)
UEN No: 53308377W Tel: 98765547
Email: joyskerworks@gmail.com

PROFOMA INVOICE

Date: 26/5/2023
Invoice No.: JW20220158
Vehicle No.: SMQ 4373 D
Make/Model: TOYOTA ESTIMA

Bill To:

LEK WEI LI 687A CHOA CHU KANG DRIVE #03-402 SINGAPORE 681687

	Description	Amount
1)	Cost of Repair (Lump sum repair as recommended by WG Appraisal Services)	\$ 12,050.00
2)	Towing	\$ 120.00
3)	Survey Fee	\$ 741.00
	Total	\$ 12,911.00

Please kindly make all cheque payable to "Joysker Works".

Company Name: Joysker Works
Company UEN No. (Paynow): 53308377W
Bank Name: OCBC CURRENT
Bank Account No.: 601-803216-001



Thank you for your business!

WG APPRAISAL SERVICES

Blk 224B, Compassvalve Walk, #07-647. Singapore 542224 Email: winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53466477J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

Date

Our Ref

Type of Inspection

Date of Re-Inspn

General Body Work

Engine No

Chassis No

Odometer

Colour

Steering

Lightings

5 mm 5 mm

5 mm

5 mm

Thread Balance

: 22 May 2023 : WG/TP/2023-84

: Third Party Claim

: 11 May 2023

: 2AZC750644

: 148701km : Black

: Good

: Serviceable

: Serviceable

: ACR507081517'

M/S: LEK WEILI

C/O JOYSKER WORKS

110 Jurong East Street 13, #05-312

Singapore 60010

REFERENCE PARTICULARS

Date of Accident : 05 May 2023

Date of Inspection : 10 May 2023

VEHICLE PARTICULARS

: SMQ4373D Registration No : TOYOTA

Make Model : ESTIMA AERAS 2.4 A

Year : 2009

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good

Foot Brake : Serviceable

Hand Brake : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

Make 225/55R17 Front Near side : Bridgestone 225/55R17

: Bridgestone Front Off Side 225/55R17 Rear Near Side : Bridgestone Rear off Side : Bridgestone 225/55R17

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear right portion.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was \$\\$\$12,050.00 nett at lump sum basis.(Subject to GST if applicable)

Size

Under normal circumstances, estimated period required for repairs: Seven (07) working days.

Enclosed Ninety-Six (96) photographs depicting damage to the vehicle.

Inspection conducted at: JOYSKER WORKS

110 Jurong East Street 13, #05-312 . Singapore 60010

In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "<u>WITHOUT PREJUDICE BASIS</u>".

VEHICLE NO: SMQ4373D

MODEL : ESTIMA AERAS 2.4 A

Our Ref : WG/TP/2023-84

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

A)		QTY	ASSESSED		ORIGINAL		REVISE
	SPARE PARTS	PC/SET	CONDITION		QUOTATION		QUOTATIO
1	REAR RH SLIDING DOOR	1	DENTED	\$	2,558.00	\$	2,558.0
2	REAR RH SLIDING DOOR TAPE	1	NECESSARY	\$	79.00	\$	79.0
3	REAR FENDER RH	1	DENTED	\$	2,331.00	\$	2,331.0
1	REAR FENDER INNER TRIM RH	1	DEFORMED/CRACKED	\$	891.00	\$	891.0
,	REAR QUARTER GLASS RH	1	SHUTTERED	\$	599.00	\$	599.0
	REAR TAILLAMP RH	1	CRACKED	\$	482.00	\$	482.0
	REAR TAILLAMP PANEL RH	1	DENTED	\$	359.00	\$	359.0
	REAR BUMPER	1	CRACKED	\$	1,385.00	\$	1,385.0
	REAR BUMPER RETAINER LH	1	NOT NECESSARY	\$	131.00	\$	-
	REAR BUMPER RETAINE RH	1	NECESSARY	\$	131.00	\$	131.0
	REAR BUMPER BRACKET LH	1	NOT NECESSARY	\$	125.00	\$	17
	REAR BUMPER BRACKET RH	1	NECESSARY	\$	125.00	\$	125.0
	AIRCON BLOWER ASSY	1	CRACKED	\$	1,914.00	\$	1,914.0
	REAR AXLE	1	BENT	\$	2,109.00	\$	2,109.0
	REAR WHEEL HUB BEARING RH	1	JAMMED	\$	552.00	\$	552.0
	REAR SHOCK ABSORBER RH	1	BENT	\$	616.00	\$	616.0
				\$	14,387.00	\$	14,131.0
			Less 25% _	\$	3,596.75	\$	3,532.7
				\$	10,790.25	\$	10,607.2
	JOINT SEALANT WINDSCREEN SEALANT	1 1	NECESSARY NECESSARY	\$ \$ \$	150.00 150.00 400.00	\$ \$ \$	130.0 130.0 340. 0
			_				
			Parts Total:	\$	11,190.25	\$	10,947.2
	A A DOVID GWA DOES A AVISG		Parts Total:	\$	11,190.25	\$	10,947.2
	LABOUR CHARGES & MISC	SVSTEM	Parts Total:	50.50		2520	
	CHECK REAR WIRING AND LIGHTNING		Parts Total : _	\$	120.00	\$	100.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AT	ND GANRISH	Parts Total :	\$	120.00 200.00	\$ \$	100.0 180.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AT REMOVE AND REFIT REAR RH QUARTE	ND GANRISH	Parts Total :	\$ \$ \$	120.00 200.00 150.00	\$ \$ \$	100.0 180.0 130.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AT REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT	ND GANRISH ER GLASS		\$ \$ \$ \$	120.00 200.00 150.00 200.00	\$ \$ \$ \$	100.0 180.0 130.0 180.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AT REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAR	ND GANRISH ER GLASS RIAGE PARTS	5	\$ \$ \$	120.00 200.00 150.00 200.00 250.00	\$ \$ \$ \$	100. 180. 130. 180. 200.
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AN REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAFTRANSFER PARTS, ATTACHMENT FROM	ND GANRISH ER GLASS RIAGE PARTS M REAR OLD S	S SLIDING DOOR TO NEW	\$ \$ \$ \$ \$	120.00 200.00 150.00 200.00 250.00 250.00	\$ \$ \$ \$ \$	100.0 180.0 130.0 180.0 200.0 200.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AN REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAFTRANSFER PARTS, ATTACHMENT FROM PANEL BEATING ON AFFECTED AREAS	ND GANRISH ER GLASS RIAGE PARTS M REAR OLD S AND RENEW	S SLIDING DOOR TO NEW	\$ \$ \$ \$ \$ \$ \$	120.00 200.00 150.00 200.00 250.00 250.00 1,800.00	\$ \$ \$ \$ \$ \$	100.0 180.0 130.0 180.0 200.0 200.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AN REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAST TRANSFER PARTS, ATTACHMENT FROM PANEL BEATING ON AFFECTED AREAS SPRAY PAINTING ON AFFECTED AREAS	ND GANRISH IR GLASS RIAGE PARTS M REAR OLD S AND RENEW S	S SLIDING DOOR TO NEW	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	120.00 200.00 150.00 200.00 250.00 250.00 1,800.00 1,500.00	\$ \$ \$ \$ \$ \$	100.0 180.0 130.0 180.0 200.0 1,600.0 1,400.0
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AN REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAFTRANSFER PARTS, ATTACHMENT FROM PANEL BEATING ON AFFECTED AREAS	ND GANRISH IR GLASS RIAGE PARTS M REAR OLD S AND RENEW S	S SLIDING DOOR TO NEW DAMAGE PARTS	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	120.00 200.00 150.00 200.00 250.00 250.00 1,800.00 1,500.00	\$ \$ \$ \$ \$ \$ \$ \$	100.6 180.6 130.6 200.6 200.6 1,600.6 1,400.6
	CHECK REAR WIRING AND LIGHTNING REMOVE, REFIT REAR LINING, TRIM AN REMOVE AND REFIT REAR RH QUARTE CHECK REAR WHEEL ALIGNMENT RMOVE AND RENEW REAR UNDERCAST TRANSFER PARTS, ATTACHMENT FROM PANEL BEATING ON AFFECTED AREAS SPRAY PAINTING ON AFFECTED AREAS	ND GANRISH IR GLASS RIAGE PARTS M REAR OLD S AND RENEW S	S SLIDING DOOR TO NEW DAMAGE PARTS	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	120.00 200.00 150.00 200.00 250.00 250.00 1,800.00 1,500.00	\$ \$ \$ \$ \$ \$	100.0 180.0 130.0 180.0 200.0 1,600.0 1,400.0

POINT OF IMPACT

The impact was confined to the rear right portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION


The repairer has agreed to undertake repair the vehicle at a lump sum basis of S\$12,050.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfull

WG APPRAISAL SERVICES


Winson Goh

Automotive Appraiser


















































































































































































































	tours Towing Services	Efficient Towing Set 402B Fernvale Lane #22-229 Singapore 792402 Ah Di Mobile: 8588 8877 Email: efficienttowing.sg@gmail.com Business Reg. No.: 53349344K	NO. 131280
		CASH SALE / JOB ORDER	Date: 9 5 23
		CASH	Jump Start/Changing of battery
	Messrs:	年型 Model No: 下STIMA 联络景码	Tyre Replacement
	Vehicle No. SMCQ75	Model No: 区S(W) 联络号码	Accident/Breakdown Multi/Basement
	时间 (日/夜) Time (day/night):	Contact No:	With Load/Cargo Box
Marine Land	b Location: S MAN	10-20 HULL 05-04	─ ☐ King Dolly
			Transport Charge
	TO: 1 DEFU C	N 6	Low Body Kit
	銀额 Cash \$	Others:	Door Opening Service
	to the state of	Tow Truck	Crane Up/Winch Out
De marie A	Authorised By: Di	Driver Name:	Collect Doc/Key
		在進行中如有任何损失或破坏,	Woodlands and Tuas Checkpoint



You have successfully logged out.

Your last login date and time was 09 May 2023, 16:02:35.

To return to ONE.MOTORING, please click here

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	YP7009A	18.19 Enquire Veh Owner Info	26.75	09 May 2023 /
			(Others) by Law Firm		16:04:06



55 Newton Road #03-02 Revenue House Singapore 307987

RECEIPT

Receipt No. : ACRA230620145137 **ARN** : ARN20230620145121

EP Reference No. : POHK1C7E GST Registration No. : M9-0008879-T

Paid By : LARA NG Date/Time : 20/06/2023 13:22:21

Paid Via : Credit/Debit Card

S/No. Transaction No. Entity Name/UEN Description Amount (SGD) Status

1 * 1230474214 HOLIE TRADING Business Profile (Biz) 5.50 Completed 53289545B

GST(SGD) 0.41 TOTAL(SGD) 5.50

This is a computer-generated receipt. No signature is required. It is important to print a copy of the receipt for future reference.

* GST Applicable.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

9 Temasek Boulevard, Suntec City Tower Two #42-01B Singapore 038989

 $\hbox{E-mail: gears-support@shift-technology.com}\\$

GST Registration: M400017735

TAX INVOICE

Date of Request: 05/06/2023 Your Ref No: 2023.0807

Dear Sir/Madam,

Date of Accident: 05/05/2023 14:30 (SGT)

Vehicle No: SMQ4373D Place of Accident: Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
YP7009A	Singapore	(31.00)	1	(28.70)
GST Amount	(2.30)			
Total Amount Due (GS	(31.00)			

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.

WG APPRAISAL SERVICES

Blk 224B, Compassvalve Walk, #07-647. Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53466477J

Our Ref:

WG/TP/2023-84

Date

22 May 2023

Invoice No:

TP/JW/2023-84

Vehicle No: Attn: SMQ4373D LEK WEI LI

Company:

JOYSKER WORKS

Address:

110 Jurong East Street 13, #05-312. Singapore 60010

Invoice

Surveyor Fee:

S\$505

Re-inspection Fee:

S\$80

Transport:

S\$60

Photographs:

S\$96/- (@ \$1 per photo, total 96 photos)

Total:

S\$741

Surveyor:

Signature:

Date:

Minson Goh

PRAIS

2 May 202