

[illegible]

Date/Time: 09.05.2023 14:59

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5896170

JC NO305554295

Customer:

NAME: COMFORT TRANSPORTATION PTE LTD
S 7010045
OMER NO. 383 SIN MING DRIVE
ESS Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

IDENT CARD NO.


REGN NO: SH 6652L	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A09.	DATE/TIME IN 05.2023 11:25
YR OF MANU. 28.07.2022	TARGET DATE
CHASSIS CODE JTDKB3FU603096875	COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 09.05.2023
NATURE: 3P 09.05.2023/C

NO LABOR CODE
10010 PB

DESCRIPTION
PANEL BEATING-SH 6552L-TP



VEHICLE PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

Vehicle No.: SH 6652L LIMITS

Vehicle No.: SH 6652L

Signature/Date

Signature/Date

Name of Service Advisor

Date

Vehicle to be kept by Security Guard

To be kept by Security Guard