

ASS. REC. BY:

REF:

CT2/23.0048301ky

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGD 9090B

Yr Regn:

07.14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Mc CLA180

C.G

1595

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

184847

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 1173422 NO 98514

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/4/23

D.O.I.

5/5/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/5 21:00 @ 27506 Curb

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS, SI

F. m. s.

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3

ANSON RD

SPRINGLEAF TOWER

SINGAPORE 079909

Contact : -

Fax No. : 62247175

Estimate : QUOT202305-000129(00)

Date : 04/05/2023

Vehicle No. : SGD9090B

Make/Model : MERCEDES BENZ CLA180 (R18 BI)

Mileage (km) : 0

Chassis No. : WDD1173422N098519

Accident Date : 29/04/2023 00:00:00

Claim No. : SNC9532R

Reference : JO202305-0183

Policy No. : 5128613673

Reg: 18/07/2014

S/No Particular Quantity Unit Price Amount S\$

LIST ITEMS :

1	LH taillamp	1.0	896.00	CM	896.00	—
2	Rear bumper	1.0	1,338.00	Bu	1,338.00	—
3	Rear bumper lower	1.0	359.00	na / bu	359.00	—
4	Rear bumper refuser	1.0	598.00	na	598.00	X
5	Rear bumper parking sensor	2.0	220.00	short / bu	440.00	2
6	Rear bumper reinforcement	1.0	715.00	R	715.00	X
7	Rear boot	1.0	2,375.00	R	2,375.00	X
8	Rear Boot emblem	1.0	72.00	na	72.00	X

List Total :

10% Discount S\$

6,793.00

679.30

6,113.70

LABOUR :

-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts

- Spray painting on affected & replace parts

1.0 750.00 750.00

1.0 850.00 850.00

1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E.

Acknowledged by Repairer Total S\$: 7,713.70

Signature: GST 8% S\$: 617.10

Date: Amount Due S\$: 8,330.80

for CITY AUTO PTE LTD