



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                   |                                                                                                                                        |                                   |                                                           |            |
|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|-----------------------------------------------------------|------------|
| MSIG INSURANCE (S) PTE LTD<br>4 SHENTON WAY #21-01<br>SGX CENTRE 2 SINGAPORE 068807 |                                                                                                                                        |                                   | Ref: CS/MSG23004836/Tvy3<br>Date: 11/05/2023<br>Code: MSG |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                   |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     | Insured Veh.                                                                                                                           | YN 6137E                          | Veh. Inspected                                            | SMB 20C    |
|                                                                                     | Policy No.                                                                                                                             |                                   | Coverage (\$)                                             | 0.00       |
|                                                                                     | Claim No.                                                                                                                              |                                   | Excess (\$)                                               | 0.00       |
|                                                                                     | Assign From                                                                                                                            | CRYSTAL LEE                       | Assign Date                                               | 11/05/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                       |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     | Make & Model                                                                                                                           |                                   | c.c                                                       | 0          |
|                                                                                     | Engine No.                                                                                                                             | HIDDEN                            | Year of Reg.                                              |            |
|                                                                                     | Chassis No.                                                                                                                            |                                   | Colour                                                    |            |
|                                                                                     | Odometer                                                                                                                               | -                                 | Steering                                                  |            |
|                                                                                     | Brakes                                                                                                                                 |                                   | Modification                                              |            |
|                                                                                     | General                                                                                                                                |                                   |                                                           |            |
| <b>3. Conditions of Tyres</b>                                                       |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     |                                                                                                                                        | Size                              | Make                                                      | Balance    |
|                                                                                     | R/H Front Tyre                                                                                                                         |                                   |                                                           | mm         |
|                                                                                     | L/H Front Tyre                                                                                                                         |                                   |                                                           | mm         |
|                                                                                     | R/H Rear Tyre                                                                                                                          |                                   |                                                           | mm         |
|                                                                                     | L/H Rear Tyre                                                                                                                          |                                   |                                                           | mm         |
| <b>4. Description of Damages</b>                                                    |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     |                                                                                                                                        |                                   |                                                           |            |
| <b>5. General Information</b>                                                       |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     | Accident Date                                                                                                                          | 09/05/2023                        | Inspection Date                                           | 11/05/2023 |
|                                                                                     | Survey held at                                                                                                                         | 310 MANDAI RD S 779404            |                                                           |            |
|                                                                                     | Repairer                                                                                                                               | TOWER TRANSIT SINGAPORE PTE. LTD. |                                                           |            |
| <b>5a. Remarks</b>                                                                  |                                                                                                                                        |                                   |                                                           |            |
|                                                                                     | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                   |                                                           |            |