



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23004840/Uny3m4 Date: 26/05/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMD 3584L	Veh. Inspected	SMW 6501G	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10022228 /JL	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	11/05/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA CERATO (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	KNAF5416MM5095780	Colour	WHITE	
Odometer	32966 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	NEXEN	6 mm	
L/H Front Tyre	225/45 R17	NEXEN	6 mm	
R/H Rear Tyre	225/45 R17	NEXEN	6 mm	
L/H Rear Tyre	225/45 R17	NEXEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/05/2023	Inspection Date	11/05/2023	
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-05 FIRST EAST CENTRE SINGAPORE 417868			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	