

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

Date: 06/06/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28915405

Claimant Vehicle No: YP7184B

Insured Vehicle No: GBF7984J

Date of Loss: 24/05/2019

Nature of Claim: TP Claim No: 594724

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP7184B

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)

Engine No: 4P10C75356

Reg. Date: 16/08/2017 (Man. Year: 2017)

Chassis No: FEB21EA21455

Colour: White

Odometer: 84797 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/85R15

Rear Tyre Size: 195/85R15

Front Left Side: Bridgestone 4 mm

Rear Left Side: Kenda 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Kenda 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 29/05/2019 Inspected At:

Cmk Motor Service Repair (sin Ming) (HQ)  
160 Sin Ming AutoCity, #08-11 Sin Ming Drive  
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: Low Sar Huei  
Surveyor

Manager: Daniel Chan Yin Leong

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Jun 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	STA INSPECTION PTE LTD/YP7184B/06/06/2019 12:07	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

STA INSPECTION PTE LTD/YP7184B/06/06/2019 12:07. Not valid without Reference section.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

STA INSPECTION PTE LTD/YP7184B/06/06/2019 12:07. Not valid without Reference section.
---

< END OF ESTIMATES >