

ASS. REC. BY:

REF:

EGZ1

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUN 52987 Yr Regn: 05, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer CLA 190 c.c. 1595

Colour:

M. D. Blue AC: Insured / Std / NI / NA

Sp. Reading:

112896 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 117 3422 N 489983

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: Pir 225/40R18

R: Continents

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

7 mm

L/Bal.

6 mm

L/Bal.

7 mm

D.O.A.

8/5/23

D.O.I.

12/5/2023

Survey held at

Des. of Damages: Fr Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Engine under cover & engine oil pump found broken at time of inspection.
Vehicle can't start, engine jammed.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Pins

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format:

Imp Sum / I.B.I. (\$



Efficient Towing Services

402B Fernvale Lane #22-229 Singapore 792402

Ah Di Mobile: 8588 8877

Email : efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

bizSAFE₃

NO. 128658

CASH SALE / JOB ORDER

Date : 08/05/23

Messrs: CHARM HOE
车牌 SLN 5298J 车型 MB CLA180
Vehicle No. 1520 Model No. 98474264
时间 (日/夜) 1520 联络号码 98474264
ime (day/night): 1520 Contact No. 98474264
Location: MORSILMS HUCP
1019 4184UN IND
额 1007 其他 1007
h \$ 1007 Others: 1007
手人 1007
horised By: 1007 Tow Truck 1007
Driver Name: 1007

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 May 2023)
 Parts: 143 MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SLN5298J/11/05/2023 17:30
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*1 pc front bumper	CM	0.00	0.00	*850.00 F
2	1		*1 pc front bumper logo	CM	0.00	0.00	*40.00 F
3	1		*1 pc front bumper reinforcement	CM	0.00	0.00	*218.00 F
4	1		*1 pc front bumper sponge		0.00	0.00	*108.00 F
5	1		*1 pc front bumper number plate garnish		0.00	0.00	*75.00 F
6	1		*1 pc front bumper centre top inner garnish		0.00	0.00	*106.00 F
7	1		*1 pc front grille base		0.00	0.00	*175.00 F
8	1		*1 pc front grille logo		0.00	0.00	*85.00 F
9	1		*1 pc front grille housing		0.00	0.00	*48.00 F
10	1		*2 pcs front grille outer mouldings @ \$57/pc		0.00	0.00	*114.00 F
11	1		*1 pc air-con condenser		0.00	0.00	*650.00 F
12	1		*1 pc radiator		0.00	0.00	*500.00 F
13	1		*1 pc radiator fan assy		0.00	0.00	*320.00 F
14	1		*1 pc front support panel		0.00	0.00	*590.00 F
15	1		*2 pcs headlamps @ \$1790/pc	o/s ?	0.00	0.00	*3,580.00 F
16	1		*2 pcs frt parking sensors @ \$108/pc	also CM	0.00	0.00	*216.00 F
Sub Total (\$\$)							7,675.00
+ Margin on L,N Items 10.00% (\$\$)							767.50
Total Parts (\$\$)							8,442.50

F=Franchise part.

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SLN5298J/11/05/2023 17:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc front number plate	35.00
2	1	1 unit coolant	30.00
Sub Total (\$\$)			65.00

Miscellaneous Items

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Estimates on Labour

No	Particulars	Lab.Type	Amount
1	Remove & refill air-con, check vacuum & refill gas	New	100.00
2	Panel beating	New	800.00
3	Putty & respray on frt bumper, reinforcement, support panel, bonnet, frt fenders	New	900.00
	To reset headlamps	New	80.00
Gross Labour Cost (\$\$)			1,880.00

Cheng Hoe Motor Pte Ltd/SLN5298J/11/05/2023 17:30. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

198J
ERGO



CHENG HOE MOTOR PTE LTD
Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ERGO
Policy No:	DMPG23005420	Date of Loss:	08/05/2023
Vehicle Reg. No.:	SLN5298J	Driveable?	UNKNOWN
Driver Age/Info:	43 / MALE	Party At Fault:	YES
TP Injury Involved?	NO	Third Party Involved?	+6598474264
Insured/Claimant:	NEO YUH HSIANG (LIANG YUXIANG)	Contact No:	
Driver:	NEO YUH HSIANG (LIANG YUXIANG)		

Make/Model:	MERCEDES-BENZ CLA180, 1.6 COUPE	Vehicle Reg. Date:	08/05/2017
Vehicle Colour:	URBAN (R18 LED) (A)	Chassis No:	WDD1173422N489483
Engine No:	BLUE		
Odometer:	27091031237795		
	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		

NOT Authorized
Murray B Gpaim
EX TBA

Description of Accident/Loss: REFER TO GIA REPORT
Remarks: VEHICLE TOW INTO YISHUN WORKSHOP ON 08/05/2023
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS		Amount
Parts		8,442.50
Miscellaneous Items		65.00
Labour		1,880.00
Paintwork Labour		0.00
Towing		0.00
Calculated Gross Total (S\$)		10,387.50
- Excess (S\$)		500.00
(S\$)		9,887.50
+ GST 8.00% (S\$)		791.00
Nett Amount (S\$)		10,678.50

This claim is handled by: DORLYN LI YAZHU

to OneMotoring

ire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

274D

Vehicle No.:

SLN5298J

Vehicle to be Exported:

No

Intended Deregistration Date:

08 May 2023

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

CLA180 COUPE URBAN (R18 LED)

Primary Colour:

Blue

Manufacturing Year:

2017

Engine No.:

27091031237795

Chassis No.:

WDD1173422N489483

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$28,815.00

Original Registration Date:

08 May 2017

First Registration Date:

08 May 2017

Transfer Count:

1

Actual ARF Paid:

\$27,341.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 May 2027

PARF Rebate Amount:

\$17,771.00

Intended COE Rebate Details

COE Expiry Date:

07 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$49,430.00

COE Rebate Amount:

\$19,755.00

Total Rebate Amount:

\$37,526.00

The information contained herein is correct as at 08 May 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Reported by 09/05/2023 18:54 (SGT)
Date of Accident Both Policyholder and Actual Driver
Exact Location of Accident 08/05/2023 01:45 (SGT)
Additional Location Information Singapore
Country/State of Loss KJE
..... Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLN5298J

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NEO YUH HSIANG (LAING YUXIANG)
NRIC No SXXXX274D
Email Address clarence_neo@yahoo.com.sg
Mobile Phone No (Phone) +65-98474264
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mercedes
Model Cla180
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1595

INSURANCE COMPANY

Name of Insurance Company ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number DMPG23005420

DRIVER

Name of Driver NEO YUH HSIANG (LAING YUXIANG)
NRIC No SXXXX274D
Date Of Birth 30/11/1979
Occupation Indoor

Describe Circumstance of the Accident


NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE

Claim under your Own Comprehensive policy. Pls check your policy for more information.

(☒) Claim Own Policy () Claim Third party () Reporting Only

() Claim OD/ TP at other workshop ()

Sketch Plan




On 080523, at around 0145hrs, while I was travelling along KJE towards BKE, the car in front brake and I was unable to brake on time and hit the rear of the vehicle, SBX440M

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time
 090523/1400

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
 (Name as in NRIC/ID card)  (YS)