ASS. BY: REF: CS/UOI23004950/Avy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SBR 99Y

Policy No.

Claims No. M11D00182305

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKF28J. Yr Regn: 2017, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 520i c.c 1998

Colour Black. A/C: Insured / Std / NI / NA

Sp.Reading 57251. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAJA12000BJ18541

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18.

R: 245/45 R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.	12/5/2023	D.O.I.	16/05/23.

Survey held at JL Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front O/S, N/S, undercarriage

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP UOI. COE Expiry :
20/6/23	Adrian confimed lump sum $19,950 (red 43,235.35, 68%)
	Estimate given during 1st Survey : Yes (✓) No ( )
	MV :
	PV :
	Nett :
	887J.

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 20/6/23-typist

Days Of Repair: 9

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: S + RS SI

Photos

Others

Report Format : TP

Lump Sum / LP / ( ) LS $19,950