

Your Ref: ACS/105/009/2021/080

Date: 17th May 2023

Our Ref: CS1/SPF23004953/Dny3m4

M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section
(Spore Police Force)
Police Logistics Base (PLB)
1 Hemmant Road
Singapore 438675
(The Motor Claims Department)

Attn: Eng Cui Fen

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FU 5002E
INSURED VEHICLE: SLA 3495M
ACCIDENT DATE: 27/08/2021**

We thank you for your instruction on 15/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FU 5002E from M/s ARC Surveyors & Adjusters.
- b) Colour damaged vehicle photographs of FU 5002E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FU 5002E
Make & Model	: Honda CB400S.F.H.V
Chassis Number	: NC391023866
Year of Registration	: 2001
Engine Capacity	: 400 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.