

Ass. Ref. BY:

REF: CS/TP23004988/Aqp3

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claim No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC39856 Yr Regn: 2017, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 Cabriolet C.C. 1595

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 98221 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2054402F465953

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habilead

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 19/04/23

Survey held at T.K.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Malaysian Vehicle</u>
	<u>final fig \$14529, 6 days. (Red \$4081, 22%)</u>
	<u>(No Lump Sum)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>2611</u>

Date/Time, File Pass to?

: Preli. Report

1) 19/07 Typist

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 4

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Inve (\$ _____)

_____ \$ + RS. _____ \$

Photos

Others

Report Format: TP

Enjin 2 hrs / L.P.P. 1 hr