



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

10 EUNOS ROAD 8  
SINGAPORE POST CENTRE #09-04A  
SINGAPORE 408600

Ref: CS/ICS23004998/Aqy3

Date: 16/05/2023

Code: ICS

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLA 1707R	<b>Veh. Inspected</b>	SLU 5536K
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	DMPC2300368H/02/CT	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	CRYSTABELLE TAN	<b>Assign Date</b>	16/05/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

--

### 5. General Information

<b>Accident Date</b>		<b>Inspection Date</b>	16/05/2023
<b>Survey held at</b>	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

ECICS LTD

10 EUNOS ROAD 8  
SINGAPORE POST CENTRE #09-04A  
SINGAPORE 408600

Ref: CS/ICS23004998/Aqy3

Date: 16/05/2023

Code: ICS

**Affiliated to Federation Internationale Des Experts En Automobile**

1. Policy Particulars :- THIRD PARTY CLAIM				
<b>Insured Veh.</b>	SLA 1707R	<b>Veh. Inspected</b>	SLU 5536K	
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	DMPC2300368H/02/CT	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	CRYSTABELLE TAN	<b>Assign Date</b>	16/05/2023	
2. Vehicle Particulars & Condition				
<b>Make &amp; Model</b>		<b>c.c</b>	0	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>		
<b>Chassis No.</b>		<b>Colour</b>		
<b>Odometer</b>	-	<b>Steering</b>		
<b>Brakes</b>		<b>Modification</b>		
<b>General</b>				
3. Conditions of Tyres				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>			mm	
<b>L/H Front Tyre</b>			mm	
<b>R/H Rear Tyre</b>			mm	
<b>L/H Rear Tyre</b>			mm	
4. Description of Damages				
5. General Information				
<b>Accident Date</b>		<b>Inspection Date</b>	16/05/2023	
<b>Survey held at</b>	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			