

Your Ref: KS.13971B.18

Date: 07th July 2023

Our Ref: CS1/LAW23005001/Any3e2

M/s Island Law LLC101 Upper Cross Street #04-04
People's Park Centre
Singapore 058357

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKL 51J
INSURED VEHICLE: SDP 1654A
ACCIDENT DATE: 08/04/2018**

We thank you for your instruction on 15/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKL 51J from M/s Prominent Appraiser Services Pte Ltd.
- b) Final Repair Bill of SKL 51J from M/s New Hock Teck Motor Pte Ltd.
- c) Singapore Accident Statement of Vehicles SKL 51J.
- d) Colour damaged vehicle photographs of SKL 51J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKL 51J
Make & Model	: Toyota Wish (A)
Chassis Number	: ZNE100387944
Year of Registration	: 2008
Engine Capacity	: 1794 cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.