



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23005002/Uvy3q2 Date: 26/06/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJZ 593A		Veh. Inspected	SMA 1418M
Policy No.			Coverage (\$)	0.00
Claim No.	C10022302/SR		Excess (\$)	0.00
Assign From	LEONG ENG MING		Assign Date	16/05/2023
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	RU11232387		Colour	WHITE
Odometer	103247 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	TOURADOR	6 mm
	L/H Front Tyre	215/60 R16	TOURADOR	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	12/05/2023	Inspection Date	19/05/2023
	Survey held at	TLM AUTOMOBILE PTE LTD 1 DEFU LANE 6, DEFU INDUSTRIAL PARK A, SINGAPORE 539365		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	