

ASS. REC. BY:

REF:

C721 230050161Kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK X 7427A

Yr Regn:

12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

C.C

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

176882

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH10459876

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

Continental 205/55R16

R: Kumho

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

J

mm

R/Bal.

7

mm

L/Bal.

P

mm

L/Bal.

7

mm

D.O.A.

12/5/23

D.O.I.

17/5/2023

Survey held at

Des. of Damages: ☒ Frt ☐ Rear ☐ O/S ☐ N/S ☐ UIC ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/5

11:50 @ 7300 Cebu

Data/Time, File Pass to?

☐

: Prel. Report

1)

Data/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

signature:

1. Towing fees	100.00	501
2. Replace/realign new parts back to the same position		
Remove damaged parts & attachments		
Cut/weld damaged panel		
Repair dented area		
Replace/realign all parts into same position	1,200.00	7001
3. To spray paint	1,100.00	10001

	8,171.42	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	813C
Vehicle Details	
Vehicle No.:	SKX7427A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 May 2023
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX533953
Chassis No.:	MR053REH104539876
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	28 Dec 2015
First Registration Date:	28 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2025
PARF Rebate Amount:	\$11,753.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$14,542.00
Total Rebate Amount:	\$26,295.00

The information contained herein is correct as at 15 May 2023

OK