



Your Ref: 23.30669

Date: 14<sup>th</sup> June 2023

Our Ref: CS3/ASM22012224/Avp3m4-1

**M/s HSBC Life (Singapore) Pte Ltd**

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFJ 719L**

**INSURED VEHICLE: SH 6229B**

**ACCIDENT DATE: 05/12/2022**

We thank you for your instruction on 17/05/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFJ 719L from CL Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SFJ 719L and SH 6229B.
- c) Final Repair Bill of SFJ 719L from M/s Top Max Auto Body Shop.
- d) Colour damaged vehicle photographs of SFJ 719L.

Pre-Repair Inspection Date: 13/12/2022 at M/s Top Max Auto Body Shop, Blk 3007 Ubi Road 1 #01-410, Singapore 408701.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SFJ 719L
Make & Model	: Renault Grand Scenic IV 1.5 Dci At Eu6
Year of Registration	: 2018
Chassis Number	: VF1RFA00061136884
Engine Capacity	: 1461 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.