

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22012224/Avp3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	25/01/2023	
	ATTN: LOH CYNTI	HIA		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6229B	Veh. Inspected	d	SFJ 719L	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04G14	Excess (\$)		0.00	
	Assign From	LOH CYNTHIA	Assign Date		06/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	RENAULT SCENIC	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	VF1RFA00061136884	Colour		BLUE	
	Odometer	29627 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55 R20	CONTINENTAL		6 mm	
	L/H Front Tyre	195/55 R20	CONTINENTAL		6 mm	
	R/H Rear Tyre	195/55 R20	CONTINENTAL		6 mm	
	L/H Rear Tyre	195/55 R20	CONTINENTAL		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION					
5. General Information						
	Accident Date	05/12/2022	Inspect Date /	Time	13/12/2022 ( 11:56 AM )	
	Survey held at	TOPMAX AUTO BODYSHOP				
		BLK 3007 UBI ROAD 1 #01-410 SINGAPORE 408701				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
	-					

Report Ref No. CS3/ASM22012224/Avp3m4

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser