

ASS. REC. BY:

Smf

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspcd Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The vch had commenced its
 repair at the time of inspection.



Est. or Market Value: \$ _____
 IDAC Accident Report: _____ Consider: Yes or No
 GIA / PR Sect: _____ Consider: Yes or No
 Est. Repair: 3 days Rest: Yes or No
 Lump Sum: _____ % 3 Vch: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: SHC8048A Yr Reg: 29 Apr 2021
 Type: MCar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: HYUNDAI IONIQ (63) cc: 1580
 Colour: Blue AC: Insured / Std / HTA
 Sp Reading: 273834 YRader: Insured / Std / HTA
 Eng No: _____
 CNr: KMHCC51CV U192985
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: NB / SRim / STD / Rlm / or
 Tyre Size: F: 195/65R15
 R: _____
 BS/DUN/EDNOVA/GY/FS/LZA/HC/OHTSU/PR/SUM/
 YOYO/YOKO or MCS+Lwice
 Front RUBal: 5 mm Rear RUBal: 5 mm
 LUBal: 5 mm RUBal: 5 mm
 D.O.A. 04/05/23 D.O.L 5/5/23 330mm
 Survey held at CDGE
 Des. of Damages: Frt / Rear / O/S / N/S / UC / Roof or
 The UC / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

		Balance:
		Yenny:
		MV:
		NV:

Date/Time, File Pass to?

☐ : Prel Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LB.L: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trips: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

3 + 12.50

Photos:

Other:

TOTAL

Date/Time: 04.05.2023 16:52

Page : 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5895441

JC NO305553701

AS
STOMER NO
RESS
(R)
(P)
COUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755


Chiang

REGN NO: SHC8048A	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 04.05.2023 15:10
YR OF MANU. 29.04.2021	TARGET DATE
CHASSIS CODE KMHC851CVLU192985	COMPLETION DATE/TIME:

JOB DESCRIPTION

Incident Date: 04.05.2023
Incident Time: 3P 04.05.2023

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedgement Slip

Exit Pass

No.: **SHC8048A** **CHIANG**

Vehicle No.: **SHC8048A**

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard