

(08/1/13) Wef
ASS REC. BY: Janu

REF:

CS/SMR 23 065 084/Rwy3

925c

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / IP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNF 8933H

at Workshop m/s MOTURWAY

of 4, 3LN RMM

Insured: SMR

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 118k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNF 8933H Yr Regn: 2022 / JUN

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Scania TIVOLI 1.6D STD c.c. 1597

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 33331 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPT 30A / WSLP325240

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/05/23

D.O.I. 8/05/23

Survey held at

MOTURWAY

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RMM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 40K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$

) S + RS SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

Tel: 6468-2200 fax: 6278-5535

GST:200000606-K RCB NO: 200000606-K

M/S : SMRT

TEL:

ATTN: MOTOR CLAIM DEPARTMENT

Your Ref No: SNF8933H

Claim Type: Third Party

Accident Date: 14/05/2023

TP Veh Reg No: SHB5020D

LABOUR \$400 SPRAY PAINT \$450

Resue
Hp 9601068

5 days

L/S

18/05/23 @ 1535

Resy after repair

Estimate No: WQT0000264

Date: 16/05/2023

Policy No:

Veh Reg No: SNF8933H

Make/Model: SSANGYONG TIVOLI

1.6D

Chassis No: KPT30A1USLP325240

Engine No:

Reg.Date:

Estimate Repair Cost to Vehicle No :

NO.	Description	Quant	List Price	Amount
			\$\$	\$\$
1	REAR BUMPER UPPER <i>de</i>	1pc	912.75	912.75
2	REAR DOOR <i>repair</i> LH	1pc	1800.00	1800.00
3	REAR FENDER WHEEL ARCH MOULDING <i>scd</i> LH	1pc	135.63	135.63
4	REAR FENDER <i>repair</i> LH	1pc	2868.375	2868.375
			TOTAL	5716.76
			LESS 10%	571.6755
			TOTAL	5145.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QTY

1pc

UNIT PRICE

40.00

LIST PRICE

40.00

TOTAL

40.00

LABOUR CHARGE

1 REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.

\$ *800* ~~1,200.00~~

2 PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)

\$ *1350* ~~1,800.00~~

3 TRANSFER DOOR MECHANISM

\$ 200.00

TOTAL

\$ 3,200.00

TOTAL PARTS

\$ 5,185.08

GRAND TOTAL

\$ 8,385.08

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	927C
Vehicle No.:	SNF8933H
Vehicle to be Exported:	No
Intended Deregistration Date:	18 May 2023
Vehicle Make:	SSANGYONG
Vehicle Model:	TIVOLI 1.6D STD 6AT 2WD ABS E6 FL
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	67391002097538
Chassis No.:	KPT30A1USLP325240
Maximum Power Output:	96.5 kW (129 bhp)
Open Market Value:	\$19,878.00
Original Registration Date:	28 Jun 2022
First Registration Date:	28 Jun 2022
Transfer Count:	0
Actual ARF Paid:	\$19,878.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2032
PARF Rebate Amount:	\$14,908.00
COE Expiry Date:	27 Jun 2032
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$68,501.00
COE Rebate Amount:	\$62,392.00
Total Rebate Amount:	\$77,300.00

The information contained herein is correct as at 18 May 2023

OK

Ssangyong Tivoli Diesel 1.6A Standard

\$109,000 Instalment \$1,098/mth

 Shortlist  Loan Calculator



POST AN AD to get the best price

START SELLING NOW

Overview Financial Photo Research

Depreciation	 \$11,980 / year
Reg. Date	23-Aug-2021 (8yrs 3mths 4days COE left)
Manufactured	 2020
Mileage	30,000 km (17.3k / year)
Transmission	Auto
Engine Cap	1,597 cc
Road Tax	 \$1,182 / year
Power	96.5 kW (129 bhp) View specs of the Ssangyong Tivoli (2019-2022)
Curb Weight	 1,425 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
COE	 \$48,002
OMV	 \$19,820
ARF	 \$19,820

Dereg Value  \$54,555 as of today