

(08/9/13) wef

ASS. REC. BY: John

REF:

csm 23005086/Rvg3

4230

ASSIGNMENT

CGE - 2025/24

From:

Date:

Estimated Cost:

Veh No:

XD 4058C

Yr Regn: 2010 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HINO SHIGUKA

C.C. 12913

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

802583

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH0SHIEEKXX/12046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROVER

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

12/05/23

D.O.I.

12/05/23

Survey held at

LPS ENHINBENH

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

To Inspect Vehicle No:

XD 4058C

at Workshop m/s

LPS ENHINBENH

of

7,800K LKST #01-381-5pax

Insured:

MSG

Policy No.

Class No.

Sum Insured:

Excess:

FHA 2000

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

28K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time Action / Instruction

REPAIR LIMIT - 23K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

LYS ENGINEERING

MAILING ADDRESS : 7 SOON LEE STREET #01-39 I SPACE S 627608

HP : 97308695 Fax : 66748965

Specialise In Repairing All Kinds Of Motor Vehicles, Spray Painting, Welding
And Agent To Claim Damages From Motor Insurance

QUOTATION

Date : 18/5/2023

To : MSIG Ins (S'pore) P/L

Attn : Mr

Fax :

Insurance Company :

Tel : 6

Fax : 6

Attn : M/V Claim Department

* Lump Sum Repair *

VEHICLE NO : XD4058C (SG SAGAWA AMEROID P/L)

We are pleased to quote you for the following services/repairs cost And Supply for the above mentioned vehicle :

ITEM	QTY	DESCRIPTION	U.PRICE	AMOUNT
			S\$	S\$
1.	1 Pc	Front Windscreen Glass	1,200.00	1,200.00
2.	1 Pc	Front Windscreen Rubber	480.00	480.00
3.	3 Pcs	Front W/Wpr Blade Assy	68.00	204.00
4.	3 Pcs	Front W/Wpr Arm Assy	140.00	420.00
5.	1 Pc	Front Top Wiper Panel	560.00	560.00
6.	1 Set	Front Inner W/Wpr Link	490.00	490.00
7.	1 Pc	Front Inner W/Wpr Motor	680.00	680.00
8.	1 Pc	Front Big Panel	1,500.00	1,500.00
9.	1 Pc	Front Grille Big	950.00	950.00
10.	2 Pcs	Front L & R Corner Panel	650.00	1,300.00
11.	2 Pcs	Front L & R Signal Lamp	220.00	440.00
12.	1 Pc	Front Hino Mark	150.00	150.00
13.	1 Pc	Front Hino Emblem	120.00	120.00
14.	1 Pc	Front 700 Emblem	95.00	95.00
15.	1 Pc	Front Bumper Assy	1,600.00	1,600.00
16.	2 Pcs	Front Head Lamp Left & Right	1,850.00	3,700.00
17.	2 Pcs	Front Bumper L & R Side Corner Cover	180.00	360.00
18.	2 Pcs	Front Bumper L & R Ctr Side Black Garnish Cover	185.00	370.00
19.	1 Pc	Front Bumper Center Black Garnish	190.00	190.00
20.	1 Pc	Front Bumper Top Grille	380.00	380.00
21.	1 Pc	Front No Plate	40.00	40.00
22.	12 Pcs	Front Corner Panel Bracket L & R	220.00	440.00
23.	12 Pcs	Front Head Lamp Bracket L & R	230.00	460.00
24.	1 Pc	Front Bumper Reinforcement	1,800.00	1,800.00
25.	1 Pc	Front Right Side Bumper Cover	120.00	120.00
26.	1 Pc	Front Right Step Garnish Bottom	230.00	230.00
27.	1 Pc	Front Right Step Aluminium Bottom	160.00	160.00
28.	1 Pc	Front Right Step Garnish Reflector	90.00	90.00
29.	2 Pcs	Front Right Step Garnish Bracket	280.00	560.00
30.	1 Pc	Front Step Garnish Bracket Rear	195.00	195.00
31.	1 Pc	Front Right Step Lower Wall	210.00	210.00
32.	1 Pc	Front Right Side Tyre	450.00	450.00
33.	2 Pcs	Front Panel Inner Lock	110.00	220.00

LYS ENGINEERING

MAILING ADDRESS : 7 SOON LEE STREET #01-39 I SPACE S 627608
HP : 97308695 Fax : 66748965

Specialise In Repairing All Kinds Of Motor Vehicles, Spray Painting, Welding
And Agent To Claim Damages From Motor Insurance

QUOTATION

Date : 18/5/2023
To : MSIG Ins (S'pore) P/L
Attn : Mr
Insurance Company :
Tel : 6
Fax : 6
Attn : M/V Claim Department

* Lump Sum Repair *

VEHICLE NO : XD4058C (SG SAGAWA AMEROID P/L)

We are pleased to quote you for the following services/repairs cost And Supply for the above mentioned vehicle :

ITEM	QTY	DESCRIPTION	U.PRICE	AMOUNT
			S\$	S\$
34.	1 Set	Front Inner Mounting Shaft ?	1,800.00	1,800.00
35.	2 Pcs	Front L & R Air Ball X	398.00	796.00
36.	1 Pc	Front Aircon Condenser ?	650.00	650.00
37.	1 Pc	Front Radiator Assy X	6,500.00	6,500.00
38.	1 Pc	Front Panel Company Logo	150.00	150.00
39.	1 Pc	Front Inner Inter Cooler (Subject To The Condition After Dismantle , Advise Later)		
SUBTOTAL				30,060.00
40.		To Refill Aircon Gas & Test For Leakages		80.00
41.		Towing Vehicle Service Charge		150.00
42.		To Spray Painting Front Body & Right Body & Inner Body		1,200.00
43.		Labour & Misc Charges :-		
		-To Remove And Replace The Above Damaged Parts, Straighten, Knock Out & To Dismantle The Front Windscreen Glass, Front Inner Mounting Shaft & Air Ball 2 Pcs		2,800.00
TOTAL				34,290.00

Please do not hesitate to contact us if you have any queries.

Thank You.

Yours faithfully



18/5/2023

Note :

Repair Work 14 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
HP 90010068
12 days
L/S
19/05/23 @ 1620
EXCESS=2000
REPAIR
Resy after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Company
Owner ID:	423D
Vehicle Details	
Vehicle No.:	XD4058C
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2023
Vehicle Make:	HINO
Vehicle Model:	SH1EEKA
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	E13CUN15137
Chassis No.:	JHDSH1EEKXXX12040
Maximum Power Output:	-
Open Market Value:	\$84,237.00
Original Registration Date:	29 Jan 2010
First Registration Date:	29 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$4,212.00
PARF Eligibility Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Vehicle Details	
COE Expiry Date:	28 Jan 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$12,443.00
COE Rebate Amount:	\$4,194.00
Total Rebate Amount:	\$4,194.00
Remarks	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 21 May 2023

OK