

Our Job Ref No 🖫 305552787 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 05/05/23 Date **FINALIZATION FORM** LKK Fax: Irfan Attn : Mr____ Vehicle Reg No. : SH9418C 26.04.2023 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-1. The repair job shall bill to: INCOME FBP1222L 2. The finalized amount shall be: (a) Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost \$0.00 (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$3,450.00 Final Lumpsum Repair cost \$3,450.00 3. Estimated normal period for repairs: working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Name : Ms. Loke YY Name Tel 62148355 Date : 65468156 Fax For Official Use Only Document Confirm By **Amount** Item Attached Remarks (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid NO 3. Survey Fees 4. LTA Search Fee \$26.75 / \$2.00 5. Medical Fees (on behalf of driver, if applicable)

6 Overrun

Remarks: