



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC23005100/Sqp3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 07-06-2023

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMM 7046A	Veh. Inspected	SHA 2627D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1220319-003	Excess (\$)	0.00
Assign From		Assign Date	28/04/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ (G2)	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KMHC851CVKU106515	Colour	BLUE
Odometer	688301	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	5 mm
L/H Front Tyre	195/65 R15	DUNLOP	5 mm
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/04/2023	Inspection Date	28/04/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------