

MOTOR SURVEY ASSIGNMENT

Date 18/05/2023 **Our Ref No.** D23001751MFCV

Accident Date 18-05-2023 Claim Type Third Party

Insured Vehicle GBJ7070A Third Party Vehicle SFP2829H

Survey Location CYCLE & CARRIAGE Contact Person YIK CHAN HOE

INDUSTRIES PTE LTD PANDAN LOOP SERVICE

CENTER 188 PANDAN LOOP (S)

128378

Contact No. 91865109 **Fax No.**

Survey Type Without Prejudice

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor

Contact Person Fax No. 68416315

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc: Workshop CYCLE & CARRIAGE INDUSTRIES PTE LTD Attention YIK CHAN HOE

Officer Incharge VICALPEH

IMPORTANT NOTE

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.