

Part: REF:

ASS. REC. BY:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspcd Vehicle No: \_\_\_\_\_

at Workshop no's \_\_\_\_\_

of \_\_\_\_\_

Insured: CTI

Policy No. \_\_\_\_\_

Claim No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehc: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: \$ \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consist<sup>n</sup>: Yes or No

GIA / PR Sect: \_\_\_\_\_ Consist<sup>n</sup>: Yes or No

Est. Repair: 3 days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC7245D Yr Reg: 28 JUL 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover L

Truck / Trailer or \_\_\_\_\_

Make: HYUNDAI I-4 cc: 1685

Colour: Yellow AC: Insured / Std / N/A

Sp. Reading: 747115 T/Radio: Insured / Std / N/A

Exp/No: \_\_\_\_\_

C/Nr: KMHLB41UM6U092570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NB / SR / STD / Rim, or

Tyre Size: F: 195 / 65 R 15

R: \_\_\_\_\_

B3 / DUN / EXHOVA / GY / FS / LZ / A / MG / OHTSU / PIR / SUM /

TOYO / YOKO or Westlake

Front R/Bal: 5 mm

L/Bal: 5 mm

D.O.A. 06/05/23

Survey held at CDGE

Des. of Damages: Fnt / Rear / O/S / N/S / UC / Rooftop or

Fnt N/S

The UC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Balance:
	Yearly:
	MV:
	NV:

Date/Time, File Pass to?  : Prell Report

: Final Report

1) \_\_\_\_\_

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / LB.L: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation

\$ + RR: \$

Photos

Other

TOTAL

Job: ARC Repair TP(CFS0)1

**JOB CARD** Sales Order: 5895791


JC NO305553709

COMER CITYCAB PTE LTD 7010070 COMER NO 383 SIN MING DRIVE Singapore SINGAPORE 575717 65551188 (R) (O) (P) UNIT CARD NO.	REGN NO: <b>SHC7245D</b>	MILEAGE
	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
	MODEL: <b>I-40</b>	DATE/TIME IN <b>06.05.2023 10:00</b>
	YR OF MANU: <b>28.07.2016</b>	TARGET DATE
	CHASSIS CODE: <b>KMHLB41UMGU092570</b>	COMPLETION DATE/TIME:

JOB DESCRIPTION

cident Date: 06.05.2023  
 TURE: 3P.06.05.23

NO                      LABOR CODE                      DESCRIPTION



ED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

gement Slip

Vehicle No.: **SHC7245D**      **JU CHINA**

Service Advisor: \_\_\_\_\_      Signature/Date: \_\_\_\_\_

turned to Service Reception upon collection

Exit Pass

Vehicle No.: **SHC7245D**

Name of Service Advisor: \_\_\_\_\_      Date: \_\_\_\_\_

To be kept by Security Guard