

(08/103) wef

ASS. REC. BY: form

REF:

CS/CT1 23005143/RIP3

008K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

4Q 47624

at Workshop m/s

CENTRAL AUTOMOTIVE

of

1, SURVIVOR RD #08-44 ECOTRA

Insured:

CT1

Policy No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

4pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

119K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

4Q 47624

Yr Regn: 2021 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU NPR 75H

c.c 593

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

61971

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAANPR75HM 7100 TRF

Can Body Be Repaired / Door / Burnt

Steering: In order / Leaked / P

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

Nil / S/Rim / S.C. Rim or

Tyre Size:

F:

215/75R17.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

02/02/23

D.O.I.

22/05/23

Survey held at

CENTRAL AUTOMOTIVE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Limit - 87K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$



ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

ATTN: MOTOR CLAIM DEPARTMENT

RE: ACCIDENT BETWEEN YQ4762Y AND GBF2967S

VEHICLE NO : YQ4762Y
MAKE MODEL : ISUZU / NPR75UH5A MT
REFERENCE : CTA-202302-02

DOA : 02-Feb-23
CLAIM TYPE : 3RD PARTY CLAIM

Sam: 94779794

LIST ITEM	QTY	LIST PRICE (\$)	REMARK
REPLACE STAINLESS STEEL DOOR FRAME <i>1/1</i>	1	\$ 3,900.00	<i>parts price check</i>
REPLACE DOOR RUBBER GASKET SET <i>act</i>	1	\$ 1,200.00	
REPLACE SIDE DOOR IMPACT RUBBER SET <i>act</i>	1	\$ 420.00	
REPLACE ALUMINIUM EXTRUSION ANODISED <i>de</i>	1	\$ 1,500.00	
FIBERGLASS REPAIR ON FRP SKIN <i>repair</i>	1	\$ 850.00	
SPRAY PAINT	1	\$ 1,000.00	<i>800</i>
LOGO WRITING	1	\$ 900.00	<i>550</i>

SUBTOTAL: \$ 9,770.00
BALANCE C/F: \$ 9,770.00

ADDITIONAL ITEMS	QTY	LIST PRICE (\$)	REMARK
LUMP SUM LABOUR TO REMOVE AND INSTALL ALL ABOVE ITEMS INCLUDING TOOL AND MATERIAL	1	\$ 900.00	<i>800</i>

SUBTOTAL: \$ 900.00
BALANCE C/F: \$ 10,670.00

MISC	QTY	LIST PRICE (\$)	REMARK
LOSS OF USE (\$300 x 8 DAYS)	1	\$ 2,400.00	<i>?</i>
LTA SEARCH FEE	1	\$ 26.75	<i>✓</i>

SUBTOTAL: \$ 2,426.75
GRAND TOTAL: \$ 13,096.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
4x 90010068
68 days
L/S
22/05/23 @ 1610
Resue after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Company
Owner ID:	008K
Vehicle Details	
Vehicle No.:	YQ4762Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 May 2023
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A MT
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	4HK10JV064
Chassis No.:	JAANPR75HM7100794
Maximum Power Output:	-
Open Market Value:	\$47,071.00
Original Registration Date:	11 Nov 2021
First Registration Date:	11 Nov 2021
Transfer Count:	0
Actual ARF Paid:	\$2,354.00
PARF Eligibility Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	10 Nov 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,024.00
COE Rebate Amount:	\$31,344.00
Total Rebate Amount:	\$31,344.00

The information contained herein is correct as at 23 May 2023

OK

Isuzu NPR75U

\$116,800 Instalment \$1,549/mth

PREMIUM AD

Shortlist

Loan Calculator

Returns as easy as CTRL + Z.
Can!
*T&Cs apply.



Overview

Financial

Photo

Research

Depreciation	 \$14,140 / year
Reg. Date	24-Aug-2021 (8yrs 3mths COE left)
Lifespan	 23-Aug-2041
Manufactured	 2021
Mileage	9,463 km (5.4k / year)
Transmission	Manual
Engine Cap	5,193 cc
Curb Weight	 3,860 kg
Fuel Type	Diesel
COE	 \$27,679
OMV	 \$37,730
ARF	 \$1,887
No. of Owners	 1
Type of Veh	Truck

Features