

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/05/2023 10:54 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	30/04/2023 16:30 (SGT)
Exact Location of Accident	Swiss View, Singapore
Additional Location Information	BETWEEN UNIT 23 & 25 @ SWISS VIEW RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF233J
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIM KOK KHENG
NRIC No	SXXXX617C
Email Address	SLIM.STEPH@GMAIL.COM
Mobile Phone No	(Phone) +65-98326362
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Forte
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	10931768

DRIVER

Name of Driver	LIM KOK KHENG
NRIC No	SXXXX617C
Date Of Birth	20/11/1969
Occupation	Indoor

Date Of Driving Pass	12/02/1990
Driving experience	33 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98326362
Alt. Phone Number	-
Email Address	SLIM.STEPH@GMAIL.COM
Address	49 SWISS VIEW
Address complement	-
Postcode	288055
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF4141U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	XU YING
Contact Number	(Phone) +65-97293417

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 2/5/23 0853
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Describe Circumstances of the Accident

Vehicle SMF233J (Kia Cerato) was parked along SWISS VIEW road on Sunday 30 Apr 2023. About 1630 hrs, a commercial vehicle (plate number GBF4141U) reversed down the slope and hit the front right bumper of Veh. SMF233J, causing a dent and dislodged bumper connectors.

Owner only discovered the following day.

GBF4141U driver left a note with hp number.


Declaration

I/We declare the foregoing particulars are true in every respect.



2/5/23 0853
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM KOK KHENG	Cust No/Name	LCV06625/LIM KOK KHENG
49 SWISS VIEW	Reg No/Reg Date	SMF233J*ECB / 21/09/201
SINGAPORE 288055	Date In/Mileage	/ 0
Contact No Mobile: 98326362	Chassis No	KNAF3416MK5013617
	Engine No	G4FGJH703969
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	03/05/2023/ 08:42	TLK	282 / Kevin Leong	12767		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER PANEL, FRT RH HEADLAMP & AFFECTED AREA REPAIR ON FRT RH FENDER							640 1920.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL & FRT RH FENDER							550 1650.00
M SUNDRY PERFORM RUST PREVENTION							X 100.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							100 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
E PNT88000 REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR							100 150.00
M SUNDRY SUNDRIES							20 50.00
M LAMP ASSY-HEAD, RH				1.00	2210.00	00.00	2210.00
M COVER-FR BUMPER				1.00	665.00	00.00	665.00
M MOULDING-FRONT BUMPER, RH				1.00	90.00	00.00	90.00
M AIR DUCT-FR BUMPER, RH				1.00	14.00	00.00	14.00
M ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	00.00	84.00
M BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	00.00	22.00
M ORNAMENT-KIA NO.115				1.00	38.00	00.00	38.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

SURVEYOR NAME: Ray - 49 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 12/06/23 @ 12:00

REMARKS: 3 days
Ray L & paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

REMARKS:

Confirm & accepted by

Nett	7,393.00
8% GST on	591.44
Total Payable	7,984.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM KOK KHENG	Cust No/Name LCV06625/LIM KOK KHENG
49 SWISS VIEW	Reg No/Reg Date SMF233J*ECB / 21/09/2018
SINGAPORE 288055	Date In/Mileage 12/06/2023/ 72478
Contact No Mobile: 98326362	Chassis/Package KNAF3416MK5013617 /#
12/06/2023	Engine No G4FGJH703969
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/06/2023/ 11:26	TLK	260 / AiTing	12767

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 640.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 550.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 100.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 280.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST TO FACILITATE REPAIR				✓ 100.00
M SUNDRY SUNDRIES				✓ 20.00
X LAMP ASSY-HEAD,RH	1.00	✓ 2210.00	00.00	2210.00
X COVER-FR BUMPER	1.00	✓ 665.00	00.00	665.00
X MOULDING-FRONT BUMPER,RH	1.00	✓ 90.00	00.00	90.00
X AIR DUCT-FR BUMPER,RH	1.00	✓ 14.00	00.00	14.00
X ABSORBER-FRONT BUMPER ENERGY	1.00	✓ 84.00	00.00	84.00
X ORNAMENT-KIA NO.115	1.00	✓ 38.00	00.00	38.00
X CLIP → <i>Supp</i>	1.00	✓ 1.00	00.00	1.00
Z TEXT TP CLAIM CHINA TAIPING GBF4141U DOA : 30.04.23 SURVEYOR RASUL-LKK 12.06.23 REPAIR 03 DAYS	10.00			10.00

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,111.00	Nett	4,801.00
Labour	1,670.00	8% GST on	384.08
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,185.08
Sundry/Others	20.00		
Total(w/o GST)	4,801.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.