

ASSIGNMENT

Ass. No. BY:

REF:

Date:

Estimate Cost:

TP RES / OD RES / EVA / INV / MV

To In Set Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claim No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

RH6537E.

Yr Regn:

2016, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV350

C.C

2488

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

28564

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1TC2E26Z0007690

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15C

R:

195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

29/03/23

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP EQ

COE Expiry :

Estimate given during : Yes ()
1st Survey : No (✓)

MV :

PV :

Nett :

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Report Format:

Report Format / J.P. / G.