

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	779E
Vehicle Details	
Vehicle No.:	SKK88J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 May 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S450L (R19 LED)
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	27682430784697
Chassis No.:	WDD2221662A384160
Maximum Power Output:	270.0 kW (362 bhp)
Open Market Value:	\$102,991.00
Original Registration Date:	19 Apr 2018
First Registration Date:	19 Apr 2018
Transfer Count:	1
Actual ARF Paid:	\$157,384.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2028
PARF Rebate Amount:	\$110,168.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$22,213.00
Total Rebate Amount:	\$132,381.00

The information contained herein is correct as at 23 May 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/05/2023 11:20 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	20/05/2023 09:15 (SGT)
Exact Location of Accident	Irrawaddy Rd, Singapore
Additional Location Information	IRRAWADDY ROAD TO SINARAN DR.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK88J
-----------------------------	--------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEONG JUN YU
NRIC No	SXXXX779E
Email Address	CHEONGJY88@ICLOUD.COM
Mobile Phone No	(Phone) +65-88000088
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	S450I
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2996

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG23005338

DRIVER

Name of Driver	CHEONG JUN YU
NRIC No	SXXXX779E
Date Of Birth	30/06/1977
Occupation	Indoor

Date Of Driving Pass	07/06/2002
Driving experience	20 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88000088
Alt. Phone Number	-
Email Address	CHEONGJY88@ICLOUD.COM
Address	68 LOYANG VIEW
Address complement	-
Postcode	507202
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH REPAIR WORKSHOP

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ5813E
Vehicle Manufacturer	Mazda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-

Contact Number (Phone) +65-83382662
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBL7323K
Vehicle Manufacturer Toyota
Vehicle Model Hiace
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver -
Contact Number (Phone) +65-97769100
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Handwritten Signature]

Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

[Handwritten Signature]

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

[Handwritten Name]

Sketch Plan



vJun2022

Describe Circumstance of the Accident

While I'm driving along irrawaddy rd when I'm about to turn right into simran dr suddenly veh B e-brake cos Veh C lost sight of the crossing pedestrians when he realised it, Veh C immediately e-brake which so crossing the sudden brake of Veh B so Veh A lost time and range to respond so it collided with Veh B.


Declaration

I/We declare the foregoing particulars are true in every respect.

 20/5/23

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

CHHAN HAN STOUT

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

*NOT WITHIN
 Survey B4 paint*

EX TBA

5 days

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Estimate : OD23/017

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469

11593.80

Date : 20/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221662A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference : LYB/SKK88J/ERGO/OD/sl
 Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
		PARTS PURCHASED :		
1.	1	FRONT BUMPER ✓	Bu 1,580.00	1,580.00
2.	1	FRONT BUMPER RETAINER/RH ✓	Sm 15.00	15.00
3.	1	FRONT BUMPER BRACKET/RH ✓	Sm 15.00	15.00
4.	1	FRONT BUMPER INSIDE PART (SIDE) ✓	cm 317.00	317.00
5.	1	FRONT BUMPER SPONGE	Sm 191.00	191.00
6.	1	FRONT BUMPER TOWING COVER/RH ✓	Sm 61.00	61.00
7.	1	FRONT BUMPER LOWER GRILLE/RH ✓	air 121.00	121.00
8.	1	FRONT BUMPER LOWER GRILLE CHROME/RH ✓	ml 163.00	163.00
9.	1	FRONT BUMPER LOWER GRILLE/CENTRE ✓	Sm 111.00	111.00
10.	1	FRONT BUMPER LOWER GRILLE CHROME/RH ✓	Sm 161.00	161.00
11.	1	FRONT FENDER/RH ✓	Ry 659.00	659.00
12.	1	FRONT FENDER INNER SHIELD/RH ✓	ml 185.00	185.00
13.	1	FRONT GRILLE	Sm 750.00	750.00
14.	1	FRONT HEADLAMP/RH ✓	cm 4,515.00	4,515.00
15.	1	FRONT HEADLAMP LOWER BRACKET/RH ✓	cm 45.00	45.00
16.	1	FRONT HEADLAMP CONTROL UNIT/RH ✓	Sm 400.00	400.00
17.	1	FRONT SENSOR	Sm 195.00	195.00
18.	1	FRONT SENSOR HOLDERS	Sm 15.00	15.00
19.	1	FRONT SENSOR WIRE HARNESS	Sm 300.00	300.00
20.	1	FRONT WIPER TANK ✓	ml 165.00	165.00
21.	1	FRONT AIR-CON PIPE (IN) ✓	Sm 435.00	435.00
22.	1	FRONT AIR-CON PIPE (OUT) <i>new pipe</i> ✓	Sm 195.00	195.00
23.	1	FRONT ABSORBER/RH	Sm 2,200.00	2,200.00
24.	1	FRONT LOWER ARM/RH	Sm 454.00	454.00

Handwritten notes and marks on the right side of the table, including '160' and various 'X' marks.

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469

Estimate : OD23/017

Date : 20/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221662A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference : LYB/SKK88J/ERGO/OD/si
 Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	FRONT KNUKLE ARM/RH		<i>Sm</i> 1,020.00 X
26.	1	FRONT BEARING HUP/RH		<i>Sm</i> 420.00 X
		Total Parts Purchased S\$:		14,688.00
		<i>15</i> 20% Of The Above Parts S\$:		2,937.60
		Based On Cost Plus S\$:		17,625.60
		SPECIAL NETT ITEMS :		
1.	10	FRONT FENDER INNER SHIELD CLIP/RH	<i>nn</i> 5.00	50.00 ✓
2.	10	RIVERTS 003 990 9497MB	<i>nn</i> 5.00	50.00 ✓
3.	1	GST BY SUPPLIER		661.34 ?
		Special Nett Total S\$:		761.34
		LABOUR :		
		TO TRANSFER FRONT SENSORS TO NEW BUMPER		60.00 ✓
		TO CHECK/ REPAIR/ REPLACE ON WIRE HARNESS <i>heate pipe</i>		120.00 <i>801</i>
		TO VACUM & TOP UP AIR-CON GAS		<i>nn</i> 80.00 X
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION		55.00 <i>201</i>
		TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT		<i>nn</i> 120.00 X
		TO CHECK ON COMPUTERISE ALIGNMENT		<i>nn</i> 120.00 X

CONTINUE / ...

LIM YEOW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469

Estimate : OD23/017

Date : 20/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221662A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference : LYB/SKK88J/ERGO/OD/si
 Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK/ REPAIR/ REPLACE THE AFFECTED AIR-CON PIPE	<i>nn</i>	180.00 <i>X</i>
		TO VACUM & TOP UP AIR-CON GAS	<i>nn</i>	120.00 <i>X</i>
		LABOUR TO CHECK/ REPAIR/ REPLACE RIGHT UNDER CARRIAGE AFFECTED APRTS	<i>nn</i>	350.00 <i>X</i>
		TO REPAIR, PANEL BEAT, RE-STRAIGHTEN ON AFFECTED PANEL, BONNET & LABOUR TO REPLACE ABOVE PARTS		1,000.00 <i>550/</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT FRT FENDER, FRT BUMPER, SENSOR & TOUCH UP ON AFFECTED BONNET ONLY		1,000.00 <i>750/</i>
		Labour Total S\$:		<u>3,205.00</u>

E. & O.E.

Total S\$: 21,591.94
 =====




for LIM YEOW BOO SPRAY PAINT CO.

3FD 3301U
SMT PAGE
GY 5F

TP: 31/01/23
TP: 16/01/2023
No of Reports:
Number of Reports:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No.: 64534177 Fax No.: 64593724
E-Mail: limyewboo@singnet.com.sg
Website: www.limyewboo.com.sg
Buss. Reg. No.: 20051400L

NOT RETURN
Activity B&P paint
EX TBA
4-5 days

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01, SUNTEC TOWER 3 SINGAPORE 038988

Estimate : OD23/017
Date : 20/05/2023
Vehicle Num. : SKK 88J
Make/Model : MERCEDES S450L-2017
Chassis/Eng# : WDD2221682A384160/27682430784697
Accident Date : 20/05/2023
Claim No. :
Reference : LYB/SKK88J/ERGO/OD/sl
Policy No. : DMPG23005338

Attention : Motor Claim Department
Contact : 68299199 Fax No. : 63338469

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	PARTS PURCHASED: ✓		
2.	1	FRONT BUMPER ✓		
3.	1	FRONT BUMPER RETAINER/RH ✓		
4.	1	FRONT BUMPER BRACKET/RH ✓		
5.	1	FRONT BUMPER INSIDE PART (SIDE) ✓		
6.	1	FRONT BUMPER SPONGE ✓		
7.	1	FRONT BUMPER TOWING COVER/RH ✓		
8.	1	FRONT BUMPER LOWER GRILLE/RH ✓		
9.	1	FRONT BUMPER LOWER GRILLE CHROME/RH ✓		
10.	1	FRONT BUMPER LOWER GRILLE/CENTRE ✓		
11.	1	FRONT BUMPER LOWER GRILLE CHROME/RH ✓		
12.	1	FRONT FENDER/RH ✓		
13.	1	FRONT FENDER INNER SHIELD/RH ✓		
14.	1	FRONT GRILLE ✓		
15.	1	FRONT HEADLAMP/RH ✓		
16.	1	FRONT HEADLAMP LOWER BRACKET/RH ✓		
17.	1	FRONT HEADLAMP CONTROL UNIT/RH ✓		
18.	1	FRONT SENSOR ✓		
19.	1	FRONT SENSOR HOLDERS ✓		
20.	1	FRONT SENSOR WIRE HARNESS ✓		
21.	1	FRONT WIPER TANK ✓		
22.	1	FRONT AIR-CON PIPE (IN) ✓ <i>sun</i>		
23.	1	FRONT AIR-CON PIPE (OUT) ✓ <i>new pipe</i>		
24.	1	FRONT ABSORBER/RH ✓		
24.	1	FRONT LOWER ARM/RH ✓		

Per 1,580.00 ✓
oil 15.00 ✓
oil 15.00 ✓ *45*
CM *sun* 317.00 ✓
sun 191.00 ✓
oil 61.00 ✓
oil 121.00 ✓
oil 163.00 ✓
sun 111.00 ✓
oil 161.00 ✓
oil 659.00 ✓
oil 185.00 ✓ *160*
sun 750.00 ✓
CM 4,515.00 ✓
CM 45.00 ✓
400.00 ✓
195.00 ✓ *sun*
15.00 ✓
300.00 ✓
oil 465.00 ✓
sun 435.00 ✓
195.00 ✓
sun 2,200.00 ✓
sun 454.00 ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *oil* after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469


Estimate : OD23/017

Date : 20/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221662A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference : LYB/SKK88J/ERGO/OD/si
 Policy No. : DMPG23005338

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK/ REPAIR/ REPLACE THE AFFECTED AIR-CON PIPE		180.00 ?
		TO VACUM & TOP UP AIR-CON GAS		120.00 ?
		LABOUR TO CHECK/ REPAIR/ REPLACE RIGHT UNDER CARRIAGE AFFECTED APRTS	nan	350.00 X
		TO REPAIR PANEL BEAT, RE-STRAIGHTEN ON AFFECTED PANEL, BONNET & LABOUR TO REPLACE ABOVE PARTS		1,000.00 400
		TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT FRT FENDER, FRT BUMPER, SENSOR & TOUCH UP ON AFFECTED BONNET ONLY		1,000.00 750
		Labour Total S\$:		3,205.00

E. & O.E.

Total S\$: 21,591.94



 for LIM YEW BOO SPRAY PAINT CO.

317012/2023
16/01/2023
No of Reports:
Number of Reports:

YEW BOO SPRAY PAINT CO.

NO. 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01, SUNTEC TOWER 3 SINGAPORE 036988

Estimate : OD23/017
Date : 20/05/2023
Vehicle Num. : SKK 88J
Make/Model : MERCEDES S450L-2017
Chassis/Eng# : WDDZ221662A384160/27682430784697
Accident Date : 20/05/2023
Claim No. :
Reference : LYB/SKK88J/ERGO/OD/1
Policy No. : DMPG23005338

Attention : Motor Claim Department
Contact : 68299189 Fax No. : 63338469

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1	FRONT KNUCKLE ARM/RH		1,020.00 X
26.	1	FRONT BEARING HUP/RH		420.00 X
		Total Parts Purchased S\$:		14,688.00
		20.00% Of The Above Parts S\$:		2,937.60
		Based On Cost Plus S\$:		17,625.60
		SPECIAL NETT ITEMS :		
1.	10	FRONT FENDER INNER SHIELD CLIP/RH	5.00	50.00
2.	10	RIVETS 003 990 9497MB	5.00	50.00
3.	1	GST BY SUPPLIER		661.34 X
		Special Nett Total S\$:		761.34
		LABOUR :		60.00
		TO TRANSFER FRONT SENSORS TO NEW BUMPER		120.00
		TO CHECK/ REPAIR/ REPLACE ON WIRE HARNESS. <i>head pipe</i>		80.00
		TO VACUM & TOP UP AIR CON GAS		55.00
		TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION		120.00
		TO RE-SET ABS SYSTEM & EARSE REGISTERED FAULT		120.00
		TO CHECK ON COMPUTERISE ALIGNMENT		120.00 X

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

ERGO INSURANCE PTE LTD
 8 TEMASEK BOULEVARD
 #04-01, SUNTEC TOWER 3 SINGAPORE 038988

Attention : Motor Claim Department
 Contact : 68299199 Fax No. : 63338469

Supplementary Estimate : SP23/017

Date : 31/05/2023
 Vehicle Num. : SKK 88J
 Make/Model : MERCEDES S450L-2017
 Chassis/Eng# : WDD2221662A384160/27682430784697
 Accident Date : 20/05/2023
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	PARTS PURCHASED : ✓		
2.	1	FRONT HOSE LINE ✓		166.00 ✓
		FRONT HEADLAMP PANEL ✓		280.00 ✓
		Total Parts Purchased S\$:		446.00
		15.00% Of The Above Parts S\$:		66.90
		Based On Cost Plus S\$:		512.90
		LABOUR :		
		LABOUR TO REPLACE THE ABOVE PARTS		200.00 X
		Labour Total S\$:		200.00

E. & O.E.

Total S\$: 712.90



[Handwritten Signature]

for LIM YEW BOO SPRAY PAINT CO.